





report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SPORT
Colour	Silver
Year of manufacture	2006
Top speed	141 mph
0 - 60 mph	8.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	206 BHP
Max. torque	435 Nm at 1.900 rpm
Engine capacity	2.720 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	35.3 mpg
CO2 emission	208 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-01-31

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/13



CV06FNE report date: 2024-03-28

MOT history

MOT expiry date	2022-02-02
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	13
Total items failed	5

MOT #15	2021-02-03 12:11
MOT test number	758780065219
Result	✓ Passed
Next expiry date	2022-02-02

MOT #14	2020-01-02 10:45
MOT test number	923460290090
Result	✓ Passed

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm inner bush (5.3.4 (a) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm inner bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2019-12-04 10:53

MOT test number 238174838990

Result X Failed

Fail Offside Rear Service brake excessively binding (1.2.1 (f))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm inner bush (5.3.4 (a) (i))

Advice Power steering close to minimum mark (2.1.5 (b) (i))

Fail Offside Rear Lower Shock absorbers has an excessively worn bush (5.3.2 (c))

Fail Nearside Rear Brake hose excessively damaged rubbing on wheel (1.1.12 (b) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement front arm inner bush (5.3.4 (a) (i))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #12 2018-11-30 11:09

MOT test number 952226198918

Advice Nearside Front Tyre slightly damaged/cracking or perishing Sidewall (5.2.3 (d) (ii))

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement Front arm (5.3.4 (a) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement

MOT #11 2017-11-15 09:30

MOT test number 127504286104

MOT #10 2016-11-30 10:25

MOT test number 754814767449

Result / Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Front arm (5.3.4 (a) (i))

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2015-11-10 12:13

MOT test number 141006692108

Result ✓ Passed

MOT #8 2014-11-29 10:00

MOT test number 815533934311

Result ✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #7 2013-12-04 16:20

MOT test number 309358833303

Result \rightarrow Passed

MOT #6 2013-12-04 14:46

MOT test number 177138833311

Result X Failed

Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #5 2013-03-05 09:30

MOT test number 479324363069

Result
✓ Passed

Advice Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4 2012-03-14 12:03

MOT test number 397664772043

CarCheck.co.uk page 5/13



CV06FNE report date: 2024-03-28

MOT #3	2011-03-15 15:12
MOT test number	928294871042
Result	✓ Passed
MOT #2	2010-03-16 15:13
MOT test number	483035970058
Result	✓ Passed
MOT #1	2009-03-04 14:55
MOT test number	842073269089
Result	✓ Passed

CarCheck.co.uk page 6/13



CV06FNE report date: 2024-03-28

Tax & MOT check



Tax expired: 1 November 2020

X MOT

Expired: 2 February 2022

Tax status	Expired at 1 November 2020
Days left	1274 days too late
MOT expiry date	2 February 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



factor scincol

CV06FNE

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this JAGUAR had different number plates.

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2006-03-13
Last registration	2021-02-03
Complete history	See info



Registration #1	2006-03-13	7 mi
Registration #2	2009-03-04	32.654 mi
Registration #3	2010-03-16	41.531 mi
Registration #4	2011-03-15	49.308 mi
Registration #5	2012-03-14	56.808 mi
Registration #6	2013-03-05	61.455 mi
Registration #7	2013-12-04	65.194 mi
Registration #8	2013-12-04	65.194 mi
Registration #9	2014-11-29	70.860 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.777 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2060 mm
Height	1447 mm
Length	4905 mm
Wheel base	2909 mm
Kerb weight	1790 kg
Max. allowed weight	2275 kg

Additional information

Fuel tank capacity	69 I
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Engine number	01265727G

CarCheck.co.uk page 13/13