



report date: 2024-03-28

General information

Make	LEXUS
Model	NX 300H PREMIER
Colour	Red
Year of manufacture	2015
Top speed	112 mph
0 - 60 mph	9.3 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	194 BHP
Max. torque	480 Nm at 4.200 rpm
Engine capacity	2.494 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	53.3 mpg
Consumption extra urban	55.4 mpg
Consumption combined	54.3 mpg
CO2 emission	121 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-02-01
Pictures	2
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-01-13
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	3
Total items failed	4

MOT #10	2023-12-19 13:26
MOT test number	460921168582
Result	✓ Passed
Next expiry date	2025-01-13

MOT #9	2023-01-06 13:02
MOT test number	785533168358
Result	✓ Passed
Advice	Offside Front Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing cracking in tread (5.2.3 (d) (ii))

MOT #8	2021-12-15 13:27
MOT test number	635736404527
Result	✓ Passed

MOT #7	2021-01-14 09:33
MOT test number	658420654169
Result	✓ Passed

**MOT #6** 2021-01-14 09:32**MOT test number** 664766660373**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #5** 2020-11-05 15:41**MOT test number** 818356073560**Result** ✓ Passed**MOT #4** 2019-11-05 16:41**MOT test number** 597816273365**Result** ✓ Passed**MOT #3** 2019-11-05 12:10**MOT test number** 132271502872**Result** ✗ Failed**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #2** 2018-11-02 09:28**MOT test number** 720101985193**Result** ✓ Passed**MOT #1** 2018-11-02 09:28**MOT test number** 436890016591**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
13 January 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	13 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	D
Single payment (12 months)	£ 140,00,-
Single six month payment	£ 77,00,-
Total payable by 12 monthly instalments	£ 147,00,-



Damage history

Check the damage history for this LEXUS. See if, where and when this LEXUS had damage and the car repair costs. We also check if this LEXUS was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra LEXUS salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LEXUS in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LEXUS? How many owners did this LEXUS have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this LEXUS had different number plates.

Number of plates	1
Current registration	RJ65HFX
Plate since	2019-09-28
Current registration	RJ65HFX
Plate since	2019-09-28

More info >



Finance check

Check if this LEXUS is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LEXUS has been settled.

If not, and you buy this LEXUS then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LEXUS is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-11-06
Last registration	2023-12-19
Complete history	See info



Registration #1	2015-11-06	23 mi
Registration #2	2018-11-02	16.733 mi
Registration #3	2018-11-02	16.733 mi
Registration #4	2019-11-05	19.224 mi
Registration #5	2019-11-05	19.224 mi
Registration #6	2020-11-05	21.196 mi
Registration #7	2020-11-05	21.196 mi
Registration #8	2020-11-05	21.196 mi
Registration #9	2020-11-05	21.196 mi
Registration #10	2020-11-05	21.196 mi
Registration #11	2020-11-05	21.196 mi
Registration #12	2020-11-05	21.196 mi

More info >



Car features

The LEXUS factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete LEXUS factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	82%
Pedestrian	69%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	1845 mm
Height	1645 mm
Length	4630 mm
Wheel base	2660 mm
Kerb weight	1785 kg
Max. allowed weight	2395 kg

Additional information

Fuel tank capacity	56 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2AR1131905