





report date: 2024-03-29

General information

Make	BMW
Model	M5
Colour	White
Year of manufacture	2012
Top speed	155 mph
0 - 60 mph	4.3 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	553 BHP
Max. torque	680 Nm at 1.500 rpm
Engine capacity	4.395 cc
Cylinders	8
Fuel type	Petrol
Consumption city	20.2 mpg
Consumption extra urban	37.2 mpg
Consumption combined	28.5 mpg
CO2 emission	232 g/km
CO2 label	L



CarCheck.co.uk page 1/12




Internet history

Entry 1

Date 2021-09-27

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

Fail

MOT expiry date	2025-04-07
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #12	2024-04-08 08:11
MOT test number	487404912919
Result	✓ Passed
Next expiry date	2025-04-07

MOT #11	2023-05-09 12:29
MOT test number	952361810650
Result	✓ Passed

MOT #10	2023-05-04 13:14
MOT test number	974705490069
Result	X Failed
Advice Front Registration plate insecure but not likely to fall off (0.1 (a))	
Fail Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Service brake binding but not excessively (1.2.1 (f))	
Fail Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 3/12



× Failed

MOT #9 2022-05-13 08:40

MOT test number 214779219673

Result ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre tread damaged

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Tyre tread damaged

Result

MOT #8 2022-05-11 12:24

MOT test number 825400089170

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

Fail Front Windscreen washer not working (3.5 (a))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre tread damaged

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

Advice Nearside Rear Tyre tread damaged

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7 2021-01-07 08:08

MOT test number 561056576140

Result
✓ Passed

CarCheck.co.uk page 4/12



MOT #6	2020-01-16 16:06
MOT test number	352060612065
Result	√ Passed
MOT #5	2018-12-13 10:38
MOT test number	800153748415
Result	✓ Passed
MOT #4	2017-12-13 10:17
MOT test number	789990812722
Result	✓ Passed
MOT #3	2017-01-13 09:36
MOT test number	270237635393
Result	✓ Passed
MOT #2	2015-12-14 09:10
MOT test number	547521885717
Result	✓ Passed
MOT #1	2014-12-16 16:16
MOT test number	909080754321
	303000734321

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	7 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	



Extra BMW salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e mier metery	
For how long did the current and previous owner(s) have this BMW? How many owners defect it in the premium report and see all owner registrations. Download the full report	
manage of the same	

	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	UK NE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-10
Last registration	2024-04-08
Complete history	See info



Registration #1	2012-01-10	6 mi
Registration #2	2014-12-16	7.937 mi
Registration #3	2015-12-14	8.973 mi
Registration #4	2017-01-13	10.814 mi
Registration #5	2017-12-13	11.978 mi
Registration #6	2018-12-13	13.520 mi
Registration #7	2020-01-16	17.522 mi
Registration #8		11.117 es
Registration #9		11.177 es
Registration #10		11.117 es
Registration #11		11.177 mi
Registration #12		11.117 es
Registration #13		11.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	95%
Children	83%
Pedestrian	78%
Safety systems	100%
Overall rating	90%
Video	see crash video



Dimensions & weight

Width	1891 mm
Height	1467 mm
Length	4910 mm
Wheel base	2964 mm
Kerb weight	1870 kg
Max. allowed weight	2410 kg

Additional information

Fuel tank capacity	80 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5 page 1	2/12

Number of axles2Engine number20440160