



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE LUNA 8V
Colour	Black
Year of manufacture	2007
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.7 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I








Internet history

Entry 1

Date	2022-04-10
Pictures	27
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-03-23
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	23
Total items failed	3

MOT #192023-03-31 13:33

MOT test number804041154087

Result	✗ Failed
MAJOR	Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
MAJOR	Central Stop lamp(s) with a multiple light source more than 1/2 not functioning (4.3.1 (a) (ii))
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))
MAJOR	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
MAJOR	Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
MAJOR	Exhaust emits visible black smoke at idle (8.2.1.2 (f))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #18** 2022-03-18 11:55**MOT test number** 604315189928**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))**MOT #17** 2021-03-04 16:37**MOT test number** 186208241754**Result** ✓ Passed**MOT #16** 2020-03-24 16:25**MOT test number** 406516991773**Result** ✓ Passed**MOT #15** 2020-03-24 10:11**MOT test number** 573336633430**Result** ✗ Failed**MAJOR** Exhaust emits excessive dense blue smoke during acceleration (8.2.1.2 (g))**Advice** Emissions not tested**MOT #14** 2019-04-09 11:00**MOT test number** 297318014959**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear Stop lamp(s) non-obligatory stop lamp not working High vision (4.3.1 (a) (ii))

**MOT #13** 2019-04-09 08:57**MOT test number** 894232163703**Result** ✗ Failed**MAJOR** Emissions not tested excessive smoke (8.2.1.2 (d))**Advice** Rear Stop lamp(s) non-obligatory stop lamp not working High vision (4.3.1 (a) (ii))**MAJOR** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #12** 2018-05-07 14:48**MOT test number** 531686391631**Result** ✓ Passed**MOT #11** 2018-05-07 14:11**MOT test number** 489080442881**Result** ✗ Failed**Fail** Nearside Headlamp not working on main beam (1.7.5a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**MOT #10** 2017-03-09 11:00**MOT test number** 883905474202**Result** ✓ Passed**MOT #9** 2017-03-08 13:42**MOT test number** 837247710182**Result** ✗ Failed**Fail** Nearside Front Headlamp aim too low adjuster not working (1.8)



MOT #8	2016-03-30 12:53
---------------	------------------

MOT test number	861591991456
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2016-03-30 12:01
---------------	------------------

MOT test number	472612799735
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2015-03-28 08:46
---------------	------------------

MOT test number	346617885048
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Rear Brake pad(s) wearing thin (3.5.1g)
---------------	---

MOT #5	2014-03-31 10:14
---------------	------------------

MOT test number	446600894050
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2013-03-25 14:12
---------------	------------------

MOT test number	186634883018
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2012-03-28 09:22
---------------	------------------

MOT test number	388238882093
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--

MOT #2	2011-03-21 11:12
---------------	------------------

MOT test number	118120981038
------------------------	--------------

Result	✓ Passed
---------------	----------



MOT #1	2010-01-15 15:12
MOT test number	441365110063
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
14 June 2023

X

MOT

Expired:
23 March 2023

Tax status	Expired at 14 June 2023
Days left	320 days too late
MOT expiry date	23 March 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LV56XZY
Plate since	2019-06-29
Current registration	 LV56XZY
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2007-01-18
Last registration	2023-03-31
Complete history	See info



Registration #1	2007-01-18	20 mi
Registration #2	2010-01-15	30.055 mi
Registration #3	2011-03-21	35.214 mi
Registration #4	2012-03-28	39.043 mi
Registration #5	2013-03-25	42.677 mi
Registration #6	2014-03-31	44.694 mi
Registration #7	2015-03-28	46.138 mi
Registration #8	2016-03-30	51.944 mi
Registration #9	2016-03-30	47.689 mi
Registration #10	2017-03-08	48.470 mi
Registration #11	2017-03-09	48.470 mi
Registration #12	2018-03-29	51.377 mi
Registration #13	2018-03-29	51.377 mi
Registration #14	2019-03-29	51.377 mi
Registration #15	2019-03-29	51.377 mi
Registration #16	2019-03-29	51.377 mi
Registration #17	2019-03-29	51.377 mi
Registration #18	2019-03-29	51.377 mi
Registration #19	2019-03-29	51.377 mi
Registration #20	2019-03-29	51.377 mi
Registration #21	2023-03-31	51.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1502 mm
Length	4081 mm
Wheel base	2516 mm
Kerb weight	1393 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats	4
Number of axles	2
Engine number	BFS 062004