



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI STYLE BLUE DRIVE
Colour	Silver
Year of manufacture	2014
Top speed	124 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	325 Nm at 2.500 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2022-01-23
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-22
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-13
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	12
Total items failed	7

MOT #13 2024-01-29 14:25**MOT test number** 901467793589**Result** ✓ Passed**Next expiry date** 2025-02-13**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2024-01-29 12:52**MOT test number** 578665513732**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #11** 2023-02-09 12:54**MOT test number** 199925153365**Result** ✓ Passed**Advice** Front Inner Brake disc worn, but not excessively Both nearside & offside. (1.1.14 (a) (i))

**MOT #10** 2023-02-09 12:54**MOT test number** 925335513871**Result** ✗ Failed**Advice** Front Inner Brake disc worn, but not excessively Both nearside & offside. (1.1.14 (a) (i))**Pass with rectification** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #9** 2022-01-14 13:02**MOT test number** 716570504829**Result** ✓ Passed**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2021-01-18 11:57**MOT test number** 553900444017**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Inner Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**MOT #7** 2020-02-08 08:38**MOT test number** 190741517979**Result** ✓ Passed**MOT #6** 2020-02-07 10:23**MOT test number** 544559862754**Result** ✗ Failed**Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**MOT #5** 2019-02-08 16:26**MOT test number** 815265225974**Result** ✓ Passed**MOT #4** 2018-01-18 10:02**MOT test number** 911221845199**Result** ✓ Passed**MOT #3** 2018-01-18 10:02**MOT test number** 338817143903**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working both (1.1.C.1d)**MOT #2** 2017-02-14 11:46**MOT test number** 606684339645**Result** ✓ Passed**MOT #1** 2017-02-13 13:17**MOT test number** 887133583594**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Front Front wheel bearing has excessive play (2.5.A.3c)



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
13 February 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	13 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-02-14
Last registration	2024-01-29
Complete history	See info



Registration #1	2014-02-14	15 mi
Registration #2	2017-02-13	32.985 mi
Registration #3	2017-02-14	32.985 mi
Registration #4	2018-01-18	41.278 mi
Registration #5	2018-01-18	41.278 mi
Registration #6	2019-02-08	52.199 mi
Registration #7	2020-02-07	63.642 mi
Registration #8	2020-02-08	63.646 mi
Registration #9	2020-02-08	63.646 mi
Registration #10	2020-02-08	63.646 mi
Registration #11	2020-02-08	63.646 mi
Registration #12	2020-02-08	63.646 mi
Registration #13	2020-02-08	63.646 mi
Registration #14	2020-02-08	63.646 mi
Registration #15	2020-02-08	63.646 mi
Registration #16	2020-02-08	63.646 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4770 mm
Wheel base	2770 mm
Kerb weight	1648 kg
Max. allowed weight	2120 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDDU341791