



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	BIPPER HDI S
Colour	Red
Year of manufacture	2010
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-13
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-29
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	20
Total items failed	11

MOT #16	2023-08-30 13:27
MOT test number	663704498058
Result	✓ Passed
Next expiry date	2024-08-29
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #15	2022-06-29 10:02
MOT test number	916551386817
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Rear Nail in tyre

**MOT #14**

2022-06-29 10:02

**MOT test number**

352376269098

**Result****✗ Failed****Minor**

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice**

Nearside Rear Nail in tyre

**Pass with rectification**

Offside Headlamp aim too high (4.1.2 (a))

**Pass with rectification**

Nearside Headlamp aim too high (4.1.2 (a))

**Advice**

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13**

2021-06-21 10:29

**MOT test number**

542639184901

**Result****✓ Passed****Advice**

Nearside Rear Shock absorbers has a slightly worn bush Upper bush (5.3.2 (c))

**Advice**

Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

**Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice**

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice**

Offside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

**MOT #12**

2021-06-18 14:14

**MOT test number**

346942769970

**Result****✗ Failed**

**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened Corroded (1.1.14 (a) (ii))

**Advice** Nearside Rear Shock absorbers has a slightly worn bush Upper bush (5.3.2 (c))

**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**MOT #11**

2018-04-13 06:39

**MOT test number**

569629574757

**Result****✓ Passed****MOT #10**

2018-04-13 06:39

**MOT test number**

396952648589

**Result****✗ Failed**

**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

**MOT #9**

2017-06-30 09:07

**MOT test number**

705237354600

**Result****✓ Passed**

**Advice** Spar wheel missing

**MOT #8** 2016-07-21 10:09**MOT test number** 621824861473**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #7** 2015-06-17 14:11**MOT test number** 376578765130**Result** ✓ Passed**MOT #6** 2015-06-15 18:29**MOT test number** 116056865187**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Rear engine mounting bracket insecure and likely to fail (6.1.D.1b)**Fail** Nearside Front Macpherson strut has excessive movement at the upper attachment (2.5.A.1c)**MOT #5** 2014-06-17 09:19**MOT test number** 127688664150**Result** ✓ Passed**MOT #4** 2014-06-14 08:21**MOT test number** 768705364196**Result** ✗ Failed**Fail** Front Exhaust has a major leak of exhaust gases (7.1.2)**MOT #3** 2013-06-24 14:13**MOT test number** 985055473114**Result** ✓ Passed



MOT #2	2013-06-19 12:18
MOT test number	835510073167
Result	✗ Failed
<div><div>Fail</div>Offside Front Macpherson strut has excessive movement in the upper support bearing assembly (2.5.B.1b)</div>	

MOT #1	2012-06-18 18:34
MOT test number	887210472115
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
29 August 2024

<b>Tax status</b>	Valid until 1 September
-------------------	-------------------------

<b>Days left</b>	125
------------------	-----

<b>MOT expiry date</b>	29 August 2024
------------------------	----------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KW59DUJ
Plate since	2019-03-28
Current registration	KW59DUJ
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-01-27
Last registration	2023-08-30
Complete history	<a href="#">See info</a>



Registration #1	2010-01-27	17 mi
Registration #2	2012-06-18	14.914 mi
Registration #3	2013-06-19	24.331 mi
Registration #4	2013-06-24	24.332 mi
Registration #5	2014-06-14	32.486 mi
Registration #6	2014-06-17	32.486 mi
Registration #7	2015-06-15	42.849 mi
Registration #8	2015-06-17	42.849 mi
Registration #9	2016-07-21	49.946 mi
Registration #10	2016-07-21	49.946 mi
Registration #11	2016-07-21	49.946 mi
Registration #12	2016-07-21	49.946 mi
Registration #13	2016-07-21	49.946 mi
Registration #14	2016-07-21	49.946 mi
Registration #15	2016-07-21	49.946 mi
Registration #16	2016-07-21	49.946 mi
Registration #17	2016-07-21	49.946 mi
Registration #18	2016-07-21	49.946 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982664026