





report date: 2024-03-28

General information

| Make | PEUGEOT |
|---------------------|-----------------|
| Model | 3008 HDI ALLURE |
| Colour | White |
| Year of manufacture | 2015 |
| Top speed | 114 mph |
| 0 - 60 mph | 13.6 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 115 BHP |
|-------------------------|---------------------|
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.560 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 48.7 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined | 57.7 mpg |
| CO2 emission | 127 g/km |
| CO2 label | D |



CarCheck.co.uk page 1/11



Internet history

Entry 1

Date 2021-02-03

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MOT history

| MOT expiry date | 2025-04-05 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 3 |
| Total items failed | 3 |

| MOT #8 | | 2024-03-25 13:31 |
|-----------|--|------------------|
| MOT test | number | 574511947733 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-04-05 |
| Advice | Nearside Front Wheel bearing has slight play (5.1.3 (a) (i)) | |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |

| MOT #7 | 2023-03-31 12:04 |
|--|-----------------------------|
| MOT test number | 875819963859 |
| Result | ✓ Passed |
| Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple larger (b) (i)) | mps or light sources (4.7.1 |

| MOT #6 | 2022-04-05 08:40 |
|-----------------|------------------|
| MOT test number | 907605924473 |
| Result | √ Passed |
| | |
| MOT #5 | 2021-04-06 14:15 |
| MOT test number | 707802602633 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/11



LF15EDV

report date: 2024-03-28

MOT #4 2020-03-17 16:44

MOT test number 807455872868

MOT #3 2020-03-17 14:44

MOT test number 740797234500

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #2 2019-03-12 08:56

MOT test number 204089077016

Result \(\sqrt{Passed} \)

MOT #1 2018-03-13 16:02

MOT test number 331509027112

CarCheck.co.uk page 4/11



Tax & MOT check



| Tax status | Valid until 1 April |
|------------------|---------------------|
| Days left | 338 |
| MOT expiry date | 5 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | D |
| Single payment (12 months) | £ 150,00,- |
| Single six month payment | £ 82,50,- |
| Total payable by 12 monthly instalments | £ 157,50,- |


CarCheck.co.uk page 5/11



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

| For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full in | | IGEOT |
|---|-------------|-------|
| | | |
| ******* | | |
| | | |
| *************************************** | | |
| ********* | | |
| *************************************** | | |
| *************************************** | | |
| | More info | > |
| Plate changes | | |
| See in this check if this PEUGEOT had different number plates. | | |
| Number of plates | | |
| Current registration | UK NEW YEAR | |
| Plate since | | |
| Current registration | OK SIES | |
| Plate since | | |
| | More info | > |

CarCheck.co.uk page 8/11



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| | |

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-03-31 |
| Last registration | 2024-03-25 |
| Complete history | See info |



| Registration #1 | 2015-03-31 | 24 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2018-03-13 | 27.193 mi |
| Registration #3 | 2019-03-12 | 37.100 mi |
| Registration #4 | 2020-03-17 | 46.113 mi |
| Registration #5 | 2020-03-17 | 46.113 mi |
| | | |
| Registration #6 | | 11.777 es |
| | | 11.777 ea 11.777 ea |
| Registration #6 | | 11.77 es 11.77 es |
| Registration #6 Registration #7 | | 11.777 es 11.777 es 11.777 es |

More info >

CarCheck.co.uk page 10/11



Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 86% |
| Children | 81% |
| Pedestrian | 31% |
| Safety systems | 97% |
| Overall rating | 75% |
| Video | see crash video |



Dimensions & weight

| Width | 1837 mm |
|---------------------|---------|
| Height | 1640 mm |
| Length | 4365 mm |
| Wheel base | 2613 mm |
| Kerb weight | 1421 kg |
| Max. allowed weight | 2030 kg |

Additional information

| Fuel tank capacity | 60 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/1 |

Number of axles 2

Engine number JBER0191476