



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D2 R-DESIGN
Colour	Silver
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	74.3 mpg
Consumption extra urban	91.1 mpg
Consumption combined	83.1 mpg
CO2 emission	88 g/km
CO2 label	A






Internet history

Entry 1

Date	2021-05-22
Pictures	17
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-24
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	9
Total items failed	10

MOT #12	2024-04-18 12:41
MOT test number	545033296403
Result	✓ Passed
Next expiry date	2025-04-24

MOT #11	2024-04-17 11:13
MOT test number	209674181792
Result	✗ Failed
Fail	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Fail	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #10	2023-04-24 09:35
MOT test number	264650625806
Result	✓ Passed
Advice	Items removed from driver's view prior to test
Advice	Clutch pedal anti slip device missing. (pedal rubber)
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #9	2022-04-25 14:15
MOT test number	856687596206
Result	✓ Passed

**MOT #8**

2022-04-23 09:31

MOT test number

218883607962

Result**✗ Failed**

Advice Offside Front Tyre worn close to legal limit/worn on edge Measured at 3.0mm. Wearing on inner edge (5.2.3 (e))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Offside Front Headlamp aim too low (4.1.2 (a))

Advice Nearside Front Tyre worn close to legal limit/worn on edge Measured at 2.5mm. Wearing on inner edge (5.2.3 (e))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #7

2021-04-21 13:32

MOT test number

916763085924

Result**✓ Passed****MOT #6**

2021-04-19 16:06

MOT test number

345111840386

Result**✗ Failed**

Fail Offside Rear Road wheel fixing missing (5.2.1 (a) (i))

Fail Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #5

2019-12-18 12:02

MOT test number

538535191657

Result**✓ Passed**

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2019-12-18 10:55**MOT test number** 840139284863**Result** ✗ Failed**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #3** 2018-12-24 14:58**MOT test number** 910664102045**Result** ✓ Passed**MOT #2** 2018-12-20 15:08**MOT test number** 736316863908**Result** ✗ Failed**Advice** Clutch pedal anti slip rubber missing**Fail** Brake pedal anti-slip provision missing (1.1.2 (c))**MOT #1** 2017-12-05 09:12**MOT test number** 915700651882**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
24 April 2025

Tax status	Valid until 1 July
Days left	63
MOT expiry date	24 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2014-12-31
Last registration	2024-04-18
Complete history	See info



Registration #1	2014-12-31	6 mi
Registration #2	2017-12-05	46.105 mi
Registration #3	2018-12-20	57.767 mi
Registration #4	2018-12-24	57.769 mi
Registration #5	2019-12-18	66.726 mi
Registration #6	2019-12-18	66.752 mi
Registration #7	2021-04-19	76.818 mi
Registration #8	2022-05-20	85.277 mi
Registration #9	2022-05-20	85.277 mi
Registration #10	2022-05-20	85.277 mi
Registration #11	2022-05-20	85.277 mi
Registration #12	2022-05-20	85.277 mi
Registration #13	2022-05-20	85.277 mi
Registration #14	2024-04-18	95.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1445 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1396 kg
Max. allowed weight	1890 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	3053756