



report date: 2024-03-29

General information

Make	CITROEN
Model	NEMO HDI 8V
Colour	Blue
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	18.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-07-14
Pictures	16
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	18
Total items failed	3

MOT #16	2023-10-31 07:57
MOT test number	928037518456
Result	✓ Passed
Next expiry date	2024-10-30

MOT #15	2023-07-18 10:19
MOT test number	646885147597
Result	✓ Passed

MOT #14	2022-07-20 15:22
MOT test number	579587932656
Result	✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2022-07-20 09:31
MOT test number	400636045527
Result	✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Shock absorbers has an excessively worn bush (5.3.2 (c))

**MOT #12** 2021-07-20 06:16**MOT test number** 248839126454**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))**MOT #11** 2020-06-26 09:46**MOT test number** 151841797737**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge all (5.2.3 (e))**MOT #10** 2019-07-01 09:28**MOT test number** 149979793392**Result** ✓ Passed**Advice** O/s/f suspension top mounting bearing faulty**Advice** All 4 tyres worn on inner edges**MOT #9** 2018-07-02 11:46**MOT test number** 458550564565**Result** ✓ Passed**Advice** Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))**MOT #8** 2018-06-28 10:24**MOT test number** 441196657805**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge all 4 (5.2.3 (e))

**MOT #7** 2017-06-09 12:50**MOT test number** 554317814507**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Rear tyres worn on edges**Advice** O/s front strut top mount stiff**MOT #6** 2016-06-10 09:37**MOT test number** 929483243475**Result** ✓ Passed**Advice** O/s front top suspension mount stiff**Advice** Centre Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**MOT #5** 2015-06-18 12:56**MOT test number** 896879565197**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2014-06-13 12:11**MOT test number** 688554464163**Result** ✓ Passed**MOT #3** 2013-06-27 11:11**MOT test number** 127458973118**Result** ✓ Passed



MOT #2	2013-06-25 12:06
MOT test number	157356273193
Result	✗ Failed
<div><div>Fail</div>Nearside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)</div>	

MOT #1	2012-06-20 16:24
MOT test number	348272772181
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
30 October 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-30
Last registration	2023-10-31
Complete history	See info



Registration #1	2009-09-30	23 mi
Registration #2	2012-06-20	38.852 mi
Registration #3	2013-06-25	44.731 mi
Registration #4	2013-06-27	44.731 mi
Registration #5	2014-06-13	50.843 mi
Registration #6	2015-06-18	57.107 mi
Registration #7	2016-06-10	61.392 mi
Registration #8	2017-06-09	62.676 mi
Registration #9	2018-06-28	64.911 mi
Registration #10	2019-06-20	66.207 mi
Registration #11	2020-06-20	67.507 mi
Registration #12	2021-06-20	68.807 mi
Registration #13	2022-06-20	70.107 mi
Registration #14	2023-06-20	71.407 mi
Registration #15	2024-06-20	72.707 mi
Registration #16	2025-06-20	74.007 mi
Registration #17	2026-06-20	75.307 mi
Registration #18	2027-06-20	76.607 mi

More info >



Dimensions & weight

Width	1816 mm
Height	1721 mm
Length	3959 mm
Wheel base	2513 mm
Kerb weight	1185 kg
Max. allowed weight	1710 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	FD982532186