



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE NAV DCI
Colour	White
Year of manufacture	2017
Top speed	116 mph
0 - 100 km/h	12.7 seconds
0 - 60 mph	12.7 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	81 kW / 110 HP / 110 BHP
Max. torque	260 Nm at 1.750 rpm
Engine capacity	1.461 cc
Cylinders	4
Fuel type	Diesel
Consumption city	68.9 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	95 g/km
CO2 label	A





Internet history

Entry 1

Date	2021-02-04
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-09-08
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #6	2023-09-07 09:09
MOT test number	702811765625
Result	✓ Passed
Next expiry date	2024-09-08
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))

MOT #5	2023-09-05 15:21
MOT test number	736028738914
Result	✗ Failed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
Fail	Offside Front Tyre has ply or cords exposed cord showing on inner edge (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened corroded (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge worn badly on inner edge (5.2.3 (e))

**MOT #4** 2022-09-05 14:11**MOT test number** 856712817137**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2021-09-07 15:06**MOT test number** 426800279402**Result** ✓ Passed**MOT #2** 2021-09-07 12:15**MOT test number** 556119418927**Result** ✗ Failed**Fail** Nearside Front Windscreen washer not working (3.5 (a))**MOT #1** 2020-09-09 14:37**MOT test number** 997238365734**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
8 September 2024

Tax status	Valid until 1 March
Days left	306
MOT expiry date	8 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
First licence fee (12 months)	£ 165,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-28
Current registration	*****
Plate since	2023-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-09-01
Last registration	2023-09-07
Complete history	See info



Registration #1	2017-09-01	28 mi
Registration #2	2020-09-09	21.985 mi
Registration #3	2021-09-07	26.481 mi
Registration #4		
Registration #5		
Registration #6		
Registration #7		
Registration #8		

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	87%
Pedestrian	71%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2058 mm
Height	1457 mm
Length	4626 mm
Wheel base	2712 mm
Kerb weight	1470 kg
Max. allowed weight	1932 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D046869