



report date: 2024-03-28

General information

Make	VOLVO
Model	V40 D2 R-DESIGN NAV PLUS
Colour	Blue
Year of manufacture	2018
Top speed	118 mph
0 - 60 mph	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	280 Nm at 2.250 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	62.8 mpg
CO2 emission	118 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-02-04
Pictures	31
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-12
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	13
Total items failed	3

MOT #5	2023-10-17 15:00
MOT test number	353824175358
Result	✓ Passed
Next expiry date	2024-11-12

MOT #4	2023-10-17 08:14
MOT test number	537554746129
Result	✗ Failed
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Fail	Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Both (5.2.3 (d) (i))

MOT #3	2022-11-09 08:55
MOT test number	284370365730
Result	✓ Passed

**MOT #2**

2021-11-11 12:50

MOT test number

555013986228

Result

✓ Passed

Advice Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre pressure warning lamp on dash**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #1**

2021-11-11 09:17

MOT test number

942119342500

Result

✗ Failed

Fail Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Tyre pressure warning lamp on dash



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
12 November 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	12 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	LJ68RFL
Plate since	2019-09-28
Current registration	LJ68RFL
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-11-13
Last registration	2023-10-17
Complete history	See info



Registration #1	2018-11-13	8 mi
Registration #2	2021-11-11	44.587 mi
Registration #3	2021-11-11	44.589 mi
Registration #4	2023-10-17	44.590 mi
Registration #5	2023-10-17	44.591 mi
Registration #6	2023-10-17	44.592 mi
Registration #7	2023-10-17	44.593 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	2041 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1468 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number	2796445
---------------	---------