



General information

Make	FORD
Model	FOCUS TITANIUM
Colour	Silver
Year of manufacture	2010
Top speed	112 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	149 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 1

Date	2021-01-30
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-05-06
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	24
Total items failed	5

MOT #16	2023-04-25 08:36
MOT test number	651898708217
Result	✓ Passed
Next expiry date	2024-05-06

MOT #15	2022-05-04 13:46
MOT test number	477430418417
Result	✓ Passed

MOT #14	2022-05-04 09:31
MOT test number	764888918324
Result	✗ Failed
MAJOR Nearside Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	
MAJOR Offside Rear fog lamp not working (4.5.1 (a) (ii))	
MAJOR Offside Position lamp light intensity significantly reduced (4.2.3 (a) (ii))	

MOT #13	2021-05-07 12:20
MOT test number	367874667749
Result	✓ Passed

**MOT #12** 2020-10-14 15:20**MOT test number** 480749374882**Result** ✓ Passed**MOT #11** 2020-10-14 13:33**MOT test number** 998265088425**Result** ✗ Failed**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #10** 2019-08-21 09:59**MOT test number** 505644135032**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rearward (5.3.4 (a) (i))**MOT #9** 2018-08-30 09:02**MOT test number** 788258415587**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner tread worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement Rear bush (5.3.4 (a) (i))**MOT #8** 2017-09-01 10:26**MOT test number** 327564940673**Result** ✓ Passed

**MOT #7** 2016-08-01 15:09**MOT test number** 472737538390**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2016-08-01 08:44**MOT test number** 462935538069**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**Fail** Rear Exhaust system not adequately supported fowling fuel tank and underside of vehicle (7.1.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2015-07-01 10:31**MOT test number** 987662785114**Result** ✓ Passed**MOT #4** 2014-04-04 15:15**MOT test number** 245744594060**Result** ✓ Passed

**MOT #3** 2014-04-04 15:15**MOT test number** 695004594062**Result** ✗ Failed**Pass with rectification** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #2** 2013-04-10 15:51**MOT test number** 228190703127**Result** ✓ Passed**Advice** Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**MOT #1** 2013-03-15 16:12**MOT test number** 377124073055**Result** ✗ Failed**Advice** Rear Rear fog lamp damaged, but still visible from a reasonable distance (1.3.2d)**Advice** Nearside Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Windscreen has damage to the swept area in excess of a 40mm circle outside zone 'A' (8.3.1d)**Advice** Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed

Tax due:
1 June 2024

✓
MOT

Expires:
6 May 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	6 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-03-05
Last registration	2023-04-25
Complete history	See info



Registration #1	2010-03-05	17 mi
Registration #2	2013-03-15	59.745 mi
Registration #3	2013-04-10	59.746 mi
Registration #4	2014-04-04	72.140 mi
Registration #5	2015-07-01	77.586 mi
Registration #6	2016-08-01	82.840 mi
Registration #7	2016-08-01	82.842 mi
Registration #8	2017-09-01	87.202 mi
Registration #9	2018-08-30	91.404 mi
Registration #10	2019-05-20	95.557 mi
Registration #11	2019-05-20	95.557 mi
Registration #12	2019-05-20	95.557 mi
Registration #13	2019-05-20	95.557 mi
Registration #14	2019-05-20	95.557 mi
Registration #15	2019-05-20	95.557 mi
Registration #16	2019-05-20	95.557 mi
Registration #17	2019-05-20	95.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1249 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	AS14346