



EOIIGHD

report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 EL H/R P/V
Colour	White
Year of manufacture	2011
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-11
Pictures	1
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2023-07-26
MOT pass rate	100 %
MOT passed	10
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #10	2022-07-15 15:19
MOT test number	643141254130
Result	✓ Passed
Next expiry date	2023-07-26
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #9	2021-07-27 13:42
MOT test number	326386287207
Result	✓ Passed

MOT #8	2020-11-18 12:00
MOT test number	999136212651
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge low 2.5mm (5.2.3 (e))
Advice	Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #7	2019-11-29 12:18
MOT test number	214385668087
Result	✓ Passed

**MOT #6** 2019-01-10 00:53**MOT test number** 329813546267**Result** ✓ Passed**MOT #5** 2018-01-08 22:49**MOT test number** 270833428559**Result** ✓ Passed**MOT #4** 2017-01-10 13:02**MOT test number** 675722078804**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Rear Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #3 2016-01-07 21:57**MOT test number** 255273350439**Result** ✓ Passed

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)

MOT #2 2015-01-09 22:36**MOT test number** 438869105042**Result** ✓ Passed



MOT #1	2014-01-24 15:37
MOT test number	627424324017
Result	✓ Passed
Advice	Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside front tyre very worn on inner edge of tread.



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-03-07
Last registration	2022-07-15
Complete history	See info



Registration #1	2011-03-07	14 mi
Registration #2	2014-01-24	49.573 mi
Registration #3	2015-01-09	56.626 mi
Registration #4	2016-01-07	61.700 mi
Registration #5	2017-01-10	66.284 mi
Registration #6	2018-01-08	70.347 mi
Registration #7	2019-01-08	75.377 mi
Registration #8	2020-01-08	80.377 mi
Registration #9	2021-01-08	85.377 mi
Registration #10	2022-01-08	90.377 mi
Registration #11	2023-01-08	95.377 mi
Registration #12	2024-01-08	100.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2374 mm
Height	2629 mm
Length	6403 mm
Kerb weight	2196 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	BS06932