



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO MYLIFE
Colour	Red
Year of manufacture	2011
Top speed	97 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	68 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	54.3 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 2

Date	2022-04-29
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-17
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	63 %
MOT passed	10
Failed MOT tests	6
Total advice items	19
Total items failed	19

MOT #16	2024-03-23 12:12
MOT test number	912890175192
Result	✓ Passed
Next expiry date	2025-03-22

MOT #15	2024-03-15 13:29
MOT test number	411398079691
Result	✗ Failed
Fail	Rear Service brake imbalanced across an axle (1.2.1 (b) (i))
Fail	Rear Exhaust has a major leak of exhaust gases Rear Silencer (6.1.2 (a))
Fail	Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

MOT #14	2023-03-17 11:47
MOT test number	279160009947
Result	✓ Passed

**MOT #13**

2023-01-09 09:52

MOT test number

743780641857

Result**✗ Failed**

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Offside headlamp damaged,not considered insecure
- Fail** Horn not working (7.7 (a))
- Advice** Offside Front brake discs and pads overheated,advise replacement
- Fail** Front Sub-frame corroded and seriously weakened (5.3.3 (b) (i))
- Fail** Offside Parking brake inoperative on one side (1.4.1 (a))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Clutch pedal rubber missing
- Fail** Rear Registration plate does not conform to the specified requirements (0.1 (d))
- Advice** Offside Front unable to check wheel bearing condition,due to brake bind
- Fail** Offside Headlamp aim too low (4.1.2 (a))
- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Advice** Rear Coil spring corroded both sides (5.3.1 (b) (i))
- Fail** Front Registration plate does not conform to the specified requirements (0.1 (d))

MOT #12

2022-01-13 14:33

MOT test number

139251055216

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2022-01-12 17:24

MOT test number

407058751133

Result**✗ Failed**

- Fail** Offside Front Service brake excessively binding (1.2.1 (f))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Advice** All 4 tyres low

MOT #10

2021-01-11 16:43

MOT test number

224643024364

Result**✓ Passed****MOT #9**

2021-01-11 12:47

MOT test number

934034749689

Result**✗ Failed**

- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #8

2019-05-13 09:34

MOT test number

512654517673

Result**✓ Passed**

- Advice** Offside Rear park brake lower than nearside
- Advice** Offside Rear Nail in tyre screw
- Advice** Offside Front tyre cut on outer sidewall but no cords showing
- Advice** Little reserve travel on park brake

**MOT #7** 2018-05-10 09:02**MOT test number** 771391568584**Result** ✓ Passed**Advice** Rear rear exhaust box corroded**MOT #6** 2018-05-09 08:44**MOT test number** 237198279071**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Rear rear exhaust box corroded**Pass with rectification** Offside Front Headlamp aim too low (1.8)**MOT #5** 2017-09-05 15:40**MOT test number** 810634985107**Result** ✓ Passed**Advice** Offside Front head light bracket broken**Advice** Rear exhaust box corroded**MOT #4** 2016-09-02 12:14**MOT test number** 666558943556**Result** ✓ Passed**MOT #3** 2015-09-03 15:54**MOT test number** 865886145287**Result** ✓ Passed



MOT #2	2015-09-03 12:10
MOT test number	438966845270
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2014-09-03 10:20
MOT test number	386476244213
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 March
Days left	307
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-09-05
Last registration	2024-03-23
Complete history	See info



Registration #1	2011-09-05	25 mi
Registration #2	2014-09-03	26.640 mi
Registration #3	2015-09-03	39.901 mi
Registration #4	2015-09-03	39.901 mi
Registration #5	2016-09-02	47.104 mi
Registration #6	2017-09-05	61.984 mi
Registration #7	2018-05-09	70.373 mi
Registration #8	2018-05-10	70.373 mi
Registration #9	2019-05-13	75.264 mi
Registration #10	2021-01-11	84.792 mi
Registration #11	2022-03-23	95.277 mi
Registration #12	2022-03-23	95.277 mi
Registration #13	2022-03-23	95.277 mi
Registration #14	2022-03-23	95.277 mi
Registration #15	2022-03-23	95.277 mi
Registration #16	2022-03-23	95.277 mi
Registration #17	2022-03-23	95.277 mi
Registration #18	2022-03-23	95.277 mi
Registration #19	2022-03-23	95.277 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1015 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	6597280