





report date: 2024-03-29

## General information

Make	MINI
Model	COOPER D
Colour	Green
Year of manufacture	2013
Top speed	122 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	99 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



EU130GZ report date: 2024-03-29

# Internet history

## Entry 2

Date 2023-12-12

Pictures 8










source: g3remarketing.co.uk

Entry 1

Date	2021-07-03	
------	------------	--


Pictures 14

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



EU130GZ report date: 2024-03-29

MOT history

MOT expiry date	2024-08-16
MOT pass rate	100 %
MOT passed	8
Failed MOT tests	0
Total advice items	9
Total items failed	0

MOT #8	2023-08-14 15:59
MOT test number	588189037502
Result	<b>✓</b> Passed
Next expiry date	2024-08-16

MOT #7		2022-08-17 14:07
MOT test	number	735465876852
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge WORN\UNEVEN P	
(i))	Registration plate lamp inoperative in the case of multiple lamps or light sour	ces 10F2 (4.7.1 (b)
Advice	Nearside Front Tyre slightly damaged TREAD\CUT (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge WORN\UNEVEN#RF	(5.2.3 (e))

MOT #6	2021-06-18 11:15
MOT test number	664271571933
Result	<b>✓</b> Passed
Advice Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

CarCheck.co.uk page 3/11



EU130GZ report date: 2024-03-29

MOT #5 2020-06-04 16:07

MOT test number 179734711653

**Result** ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #4 2018-07-17 15:44

**MOT test number** 660252043563

**Result** ✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm worn on outer edge (5.2.3 (e))

MOT #3 2017-12-21 11:21

**MOT test number** 404453873947

**Result** ✓ Passed

MOT #2 2017-01-10 11:25

**MOT test number** 450256434922

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2016-01-28 15:00

**MOT test number** 734626839868

Result \( \sqrt{Passed} \)

CarCheck.co.uk page 4/11



report date: 2024-03-29

## Tax & MOT check



Tax status	Valid until 1 September
Days left	124
MOT expiry date	16 August 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-29

## Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

## Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

**EU130GZ** 

report date: 2024-03-29

# For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>.

## Plate changes

More info >

More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

## Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

**Contact info** 

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

# Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-03-12
Last registration	2023-08-14
Complete history	See info



Registration #1	2013-03-12	8 mi
Registration #2	2016-01-28	47.478 mi
Registration #3	2017-01-10	57.603 mi
Registration #4	2017-12-21	66.832 mi
Registration #5	2018-07-17	72.312 mi
Registration #6		11.777 au
_		
Registration #7		71.777 es
Registration #7 Registration #8		11.777 ea
-		11,777 ea 11,777 ea 11,777 ea

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

# Car features

50225	Air conditioning
50295	
60482	
60501	
0566	
60567	
60569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1683 mm
Height	1407 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1090 kg
Max. allowed weight	1540 kg

# Additional information

Fuel tank capacity	40
Fuel delivery	Direct Injection
Number of doors	3
Number of seats CarCheck.co.uk	4 page 11/1:

Number of axles 2

Engine number 70208446