



report date: 2024-03-28

General information

Make	VAUXHALL
Model	ANTARA EXCLUSIV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	160 g/km
CO2 label	G





Internet history

Entry 2


Date	2023-10-07
Pictures	35
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-08-20
Pictures	20
Listing price	View report



source: [cargurus.co.uk](#)



MOT history

MOT expiry date	2024-07-10
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	12
Total items failed	0

MOT #11	2023-07-05 15:46
MOT test number	132983120047
Result	✓ Passed
Next expiry date	2024-07-10
Advice	Front Brake pad(s) wearing thin N/S/F and O/S/F (1.1.13 (a) (ii))
Advice	Rear Brake pad(s) wearing thin N/S/R and O/S/R (1.1.13 (a) (ii))

MOT #10	2023-07-04 10:30
MOT test number	148191726683
Result	✗ Failed
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Rear Brake pad(s) wearing thin N/S/R and O/S/R (1.1.13 (a) (ii))
Advice	Front Brake pad(s) wearing thin N/S/F and O/S/F (1.1.13 (a) (ii))

MOT #9	2022-07-04 11:48
MOT test number	384575985459
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #8** 2022-07-02 09:42**MOT test number** 759129265750**Result** ✗ Failed**MAJOR** Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #7** 2021-07-10 09:35**MOT test number** 128544867586**Result** ✓ Passed**MOT #6** 2020-07-11 08:57**MOT test number** 576753901887**Result** ✓ Passed**MOT #5** 2019-07-13 09:25**MOT test number** 439976406842**Result** ✓ Passed**MOT #4** 2019-07-13 08:42**MOT test number** 703805523661**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-07-13 13:05**MOT test number** 458545078174**Result** ✓ Passed



MOT #2	2017-07-05 09:24
MOT test number	802876688999
Result	✓ Passed

MOT #1	2016-07-11 09:26
MOT test number	992040572213
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 July 2024

Tax status	Valid until 1 April
Days left	337
MOT expiry date	10 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 PK13YEV
Plate since	2019-03-29
Current registration	 PK13YEV
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-29
Last registration	2023-07-05
Complete history	See info



Registration #1	2013-06-29	24 mi
Registration #2	2016-07-11	22.682 mi
Registration #3	2017-07-05	40.095 mi
Registration #4	2018-07-13	60.959 mi
Registration #5	2019-07-13	70.039 mi
Registration #6	2019-07-13	70.039 mi
Registration #7	2020-07-11	78.424 mi
Registration #8	2020-07-11	78.424 mi
Registration #9	2020-07-11	78.424 mi
Registration #10	2020-07-11	78.424 mi
Registration #11	2020-07-11	78.424 mi
Registration #12	2020-07-11	78.424 mi
Registration #13	2020-07-11	78.424 mi
Registration #14	2020-07-11	78.424 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1836 kg
Max. allowed weight	2505 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 263998K LNQ