



report date: 2024-03-29

General information

Make	CITROEN
Model	BERLINGO 750 LX L2 HDI
Colour	White
Year of manufacture	2014
Top speed	99 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.500 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	55.4 mpg
Consumption combined	51.4 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-05-23
Pictures	4
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-20
MOT pass rate	58 %
MOT passed	7
Failed MOT tests	5
Total advice items	31
Total items failed	4

MOT #12	2024-04-19 10:17
MOT test number	414075853384
Result	✓ Passed
Next expiry date	2025-04-20
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #11	2024-04-19 10:17
MOT test number	360303862896
Result	✗ Failed
Pass with rectification	Nearside Rear Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Rear Registration plate lamp inoperative in the case of a single lamp or all lamps Both lamps inoperative (4.7.1 (b) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #10	2023-04-12 11:50
MOT test number	396243345526
Result	✓ Passed
Minor	Offside Rear Position lamp insecure (4.2.1 (c) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge bald outer edge (5.2.3 (e))
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #9** 2023-04-12 10:04**MOT test number** 454212412647**Result** ✗ Failed**MAJOR** Offside Rear Rear reflector reflecting white to the rear (4.8.2 (a) (ii))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge bald outer edge (5.2.3 (e))**MAJOR** Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Minor** Offside Rear Position lamp insecure (4.2.1 (c) (i))**MAJOR** Offside Rear Rear reflector defective or damaged by more than 50% of the reflecting surface (4.8.1 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #8** 2022-04-21 14:49**MOT test number** 977656559337**Result** ✓ Passed**MOT #7** 2022-04-21 09:13**MOT test number** 610746315403**Result** ✗ Failed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both discs worn (1.1.14 (a) (ii))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened inner face scored (1.1.14 (a) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge bald outer edge, 2mm-3mm across tread (5.2.3 (e))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #6** 2021-01-23 09:43**MOT test number** 961289193657**Result** ✓ Passed**Advice** Undertray not fully secure (8.1.1 (b) (i))

**MOT #5** 2021-01-16 09:41**MOT test number** 767659541688**Result** ✗ Failed

- MAJOR** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- MAJOR** Electronic stability control warning lamp indicates a fault (7.12 (e))
- MAJOR** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Main beam tell-tale not working (4.9.1 (a) (ii))
- MAJOR** Central Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Undertray not fully secure (8.1.1 (b) (i))

MOT #4 2020-01-11 08:47**MOT test number** 939534431344**Result** ✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #3 2019-01-05 09:38**MOT test number** 892951305431**Result** ✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



MOT #2	2019-01-05 09:38
MOT test number	229318839766
Result	✗ Failed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a))

MOT #1	2017-12-30 13:38
MOT test number	469226959688
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Centre brake light not working



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
20 April 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	20 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-04-30
Last registration	2024-04-19
Complete history	See info



Registration #1	2014-04-30	13 mi
Registration #2	2017-12-30	31.746 mi
Registration #3	2019-01-05	43.851 mi
Registration #4	2019-01-05	43.851 mi
Registration #5	2020-01-11	58.562 mi
Registration #6	2021-01-23	70.293 mi
Registration #7	2022-05-20	85.277 mi
Registration #8	2022-05-20	85.277 mi
Registration #9	2022-05-20	85.277 mi
Registration #10	2022-05-20	85.277 mi
Registration #11	2022-05-20	85.277 mi
Registration #12	2022-05-20	85.277 mi
Registration #13	2022-05-20	85.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	6
Number of seats	3
Engine number	JBEM0265727