






report date: 2024-03-28

General information

| Make | NISSAN |
|---------------------|----------------|
| Model | NV200 DCI SE |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 98 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 85 BHP |
|-------------------------|---------------------|
| Max. torque | 200 Nm at 2.000 rpm |
| Engine capacity | 1.461 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 49.6 mpg |
| Consumption extra urban | 57.7 mpg |
| Consumption combined | 54.3 mpg |



CarCheck.co.uk page 1/13



Internet history

Entry 1


Date 2022-01-13

Pictures 29

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date | 2025-01-25 |
|--------------------|------------|
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 22 |
| Total items failed | 8 |

| MOT #14 | | 2024-01-26 16:54 |
|-----------|--|------------------|
| MOT test | number | 888366956496 |
| Result | | ✓ Passed |
| Next expi | ry date | 2025-01-25 |
| Advice | Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) | |
| Advice | Vehicle has auxillary earth fitted but is not secure | |
| Advice | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) | |
| Advice | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Advice | Oil leak, but not excessive (8.4.1 (a) (i)) | |

CarCheck.co.uk page 3/13



MOT #13 2024-01-24 16:06

MOT test number 289448697131

Result

× Failed

Fail Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Fail Offside Front Headlamp aim too far to the right (4.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Vehicle has auxillary earth fitted but is not secure

Fail Front All position lamps light intensity significantly reduced not working (4.2.3 (a) (ii))

Fail Rear Stop lamp(s) all not working (4.3.1 (a) (iii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #12 2023-01-25 10:11

MOT test number 775735014452

Result \(\sqrt{Passed} \)

Advice Offside Rear Anti-roll bar linkage ball joint has slight play DROP LINK (5.3.4 (a) (i))

MOT #11 2021-12-18 07:23

MOT test number 994171549566

Result

✓ Passed

MOT #10 2021-01-13 14:30

MOT test number 131553336864

Result ✓ Passed

CarCheck.co.uk page 4/13



MOT #9 2019-05-31 11:58

MOT test number 160442194216

MOT #8 2018-06-04 15:18

MOT test number 980276852267

Result

✓ Passed

MOT #7 2018-06-04 11:23

MOT test number 730919431979

Result X Failed

Fail Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Service brake efficiency less than 50% of the required value (1.2.2 (a) (ii))

MOT #6 2017-06-05 14:50

MOT test number 358131670176

Result

Passed

Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Offside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2016-03-30 11:30

MOT test number 438778101393

Result ✓ Passed

CarCheck.co.uk page 5/13



Advice

EY10HCJ report date: 2024-03-28

MOT #4 2015-04-01 16:36 **MOT** test number 159531695408 Result ✓ Passed **Advice** Offside Front Brake pad(s) wearing thin (3.5.1g) **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Advice Parking brake lever has little reserve travel (3.1.6b) Advice Nearside Front Brake pad(s) wearing thin (3.5.1g) Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #3

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Brake hydraulic reservoir fluid close to minimum level (3.6.G.1b)

MOT test number

Result

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Offside Front Front position lamp(s) not working (1.1.A.3b)

 MOT #1
 2013-03-27 10:17

 MOT test number
 128616683438

 Result
 ✓ Passed

CarCheck.co.uk page 6/13



Tax & MOT check



| Tax status | Valid until 1 March |
|------------------|---------------------|
| Days left | 306 |
| MOT expiry date | 25 January 2025 |
| Full MOT history | See MOT history |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

| For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full is | |
|---|--|
| | |
| *************************************** | |
| | |
| | |
| | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Current registration | UK NE |
| Plate since | |
| Current registration | OK ON THE OWNER OF THE OWNER OW |
| Plate since | |
| | More info > |

CarCheck.co.uk page 10/13



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-03-30 |
| Last registration | 2024-01-26 |
| Complete history | See info |



| Registration #1 | 2010-03-30 | 6 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-03-27 | 45.381 mi |
| Registration #3 | 2014-04-03 | 58.786 mi |
| Registration #4 | 2015-04-01 | 66.560 mi |
| Registration #5 | 2016-03-30 | 73.202 mi |
| Registration #6 | 2017-06-05 | 81.894 mi |
| Registration #7 | 2018-06-04 | 86.921 mi |
| Registration #8 | 2018-06-04 | 86.921 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 9.70 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 9.70 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | 11.177 es |

More info >

CarCheck.co.uk page 12/13



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1695 mm |
|---------------------|---------|
| Height | 1860 mm |
| Length | 4400 mm |
| Kerb weight | 1269 kg |
| Max. allowed weight | 2000 kg |

Additional information

| Fuel tank capacity | 55 I |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 2 |
| Number of axles CarCheck.co.uk | 2 page 13/13 |

Engine number

07188D