



report date: 2024-03-28

General information

Make	JAGUAR
Model	XF D V6 S PREMIUM LUXURY SPORTBRAKE
Colour	Grey
Year of manufacture	2014
Top speed	155 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	275 BHP
Max. torque	600 Nm at 2.000 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-08-11
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	11
Total items failed	19

MOT #8 2023-08-12 13:23

MOT test number 887493132900

Result ✓ Passed

Next expiry date 2024-08-11

Advice Offside Front Coil spring corroded replaced with second hand part (5.3.1 (b) (i))**Advice** Covers fitted-under trays fitted-vehicle structure and suspension related components corroded-x2 front brake ferrules corroded-x2 rear link boots slightly split

MOT #7 2023-08-09 15:15

MOT test number 841170383520

Result ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))**Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Covers fitted-under trays fitted-vehicle structure and suspension related components corroded-x2 front brake ferrules corroded-x2 rear link boots slightly split

**MOT #6**

2023-08-01 16:42

MOT test number

386486912713

Result**✗ Failed**

Advice Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))

Fail Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Offside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Road wheel more than one fixing missing (5.2.1 (a) (ii))

Fail Offside Front Service brake excessively fluctuating (1.2.1 (e))

Advice Vehicle structure & suspension related components corroded

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Windscreen washer not working (3.5 (a))

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))

Fail Nearside Rear Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Service brake excessively fluctuating (1.2.1 (e))

MOT #5

2022-06-14 14:35

MOT test number

771640029457

Result**✓ Passed**

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2022-06-10 13:09**MOT test number** 253196326708**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))**Advice** Brake wear indicator light illuminated**Advice** Offside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #3** 2021-06-18 14:53**MOT test number** 956902001282**Result** ✓ Passed**MOT #2** 2018-03-23 09:57**MOT test number** 274113847072**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2017-03-24 12:51**MOT test number** 506204219504**Result** ✓ Passed



Tax & MOT check

✗
Untaxed

Tax expired:
19 February 2023

✓
MOT

Expires:
11 August 2024

Tax status

Expired at 19 February 2023

Days left

434 days too late

MOT expiry date

11 August 2024

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	LV14BCX
Plate since	2024-03-28
Current registration	LV14BCX
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2014-03-27
Last registration	2023-08-12
Complete history	See info



Registration #1	2014-03-27	21 mi
Registration #2	2017-03-24	104.639 mi
Registration #3	2018-03-23	135.247 mi
Registration #4	2019-03-22	151.277 mi
Registration #5	2021-06-18	143.648 mi
Registration #6	2022-03-22	151.277 mi
Registration #7	2022-03-22	151.277 mi
Registration #8	2022-03-22	151.277 mi
Registration #9	2022-03-22	151.277 mi
Registration #10	2023-08-12	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	79%
Children	73%
Pedestrian	62%
Safety systems	71%
Overall rating	74%
Video	see crash video



Dimensions & weight

Width	1877 mm
Height	1480 mm
Length	4966 mm
Wheel base	2909 mm
Kerb weight	1880 kg
Max. allowed weight	2440 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0827292306DT