



TOYOTA



report date: 2024-03-29

General information

Make	TOYOTA
Model	PRIUS VVT-I T SPIRIT
Colour	Silver
Year of manufacture	2007
Top speed	106 mph
0 - 60 mph	10.9 seconds
Gearbox	4 speed CVT

Engine & fuel consumption

Power	76 BHP
Max. torque	115 Nm at 4.000 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	56.5 mpg
Consumption extra urban	67.3 mpg
Consumption combined	65.7 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-05
Pictures	8
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-12-18
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	21
Total items failed	6

MOT #16	2023-12-16 11:38
MOT test number	916392767822
Result	✓ Passed
Next expiry date	2024-12-18
Advice	Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Minor	Front Headlamp lens slightly defective both (4.1.1 (b) (i))
Advice	Nearside Front Nail in tyre

MOT #15	2022-12-03 12:01
MOT test number	167467742073
Result	✓ Passed
Advice	Nearside Front Inner Tyre wearing slightly
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge 2.8mm and cracking (5.2.3 (e))
Advice	Offside Front Inner Tyre wearing slightly

**MOT #14**

2021-12-11 12:08

MOT test number

253849642504

Result

✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear wishbone bush (5.3.4 (a) (i))**MOT #13**

2020-12-15 12:33

MOT test number

578251517113

Result

✓ Passed

MOT #12

2020-12-14 14:56

MOT test number

593769043550

Result

✗ Failed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #11**

2019-12-14 09:54

MOT test number

851303835013

Result

✓ Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #10** 2018-12-11 12:05**MOT test number** 446403044418**Result** ✓ Passed**MOT #9** 2017-12-04 12:02**MOT test number** 849314075843**Result** ✓ Passed**MOT #8** 2016-12-13 14:46**MOT test number** 274762534961**Result** ✓ Passed**MOT #7** 2016-12-13 10:05**MOT test number** 132565049849**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Front brake disc in such a condition that it is seriously weakened inner faces corroded (3.5.1i)**MOT #6** 2015-12-16 09:59**MOT test number** 144762899257**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2014-12-08 15:18**MOT test number** 775122844329**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-12-16 14:42**MOT test number** 488840853303**Result** ✓ Passed**MOT #3** 2012-12-19 09:52**MOT test number** 367344852394**Result** ✓ Passed**MOT #2** 2011-12-14 09:37**MOT test number** 105138441382**Result** ✓ Passed**MOT #1** 2010-12-14 16:34**MOT test number** 100318940363**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
18 December 2024

Tax status	Valid until 1 February
Days left	278
MOT expiry date	18 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	B
Single payment (12 months)	£ 10,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 10,50,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	MT57XON
Plate since	2024-03-29
Current registration	MT57XON
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-12-17
Last registration	2023-12-16
Complete history	See info



Registration #1	2007-12-17	17 mi
Registration #2	2010-12-14	43.091 mi
Registration #3	2011-12-14	53.276 mi
Registration #4	2012-12-19	64.973 mi
Registration #5	2013-12-16	73.488 mi
Registration #6	2014-12-08	80.376 mi
Registration #7	2015-12-16	88.076 mi
Registration #8	2016-12-13	92.815 mi
Registration #9	2016-12-13	92.815 mi
Registration #10	2016-12-13	92.815 mi
Registration #11	2016-12-13	92.815 mi
Registration #12	2016-12-13	92.815 mi
Registration #13	2016-12-13	92.815 mi
Registration #14	2016-12-13	92.815 mi
Registration #15	2016-12-13	92.815 mi
Registration #16	2016-12-13	92.815 mi
Registration #17	2016-12-13	92.815 mi
Registration #18	2016-12-13	92.815 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1725 mm
Height	1490 mm
Length	4450 mm
Wheel base	2700 mm
Kerb weight	1325 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NZU155719