



PEUGEOT




report date: 2024-03-29

General information

Make	PEUGEOT
Model	BOXER HDI 335 L3H2 PROFESSIONAL P/V
Colour	White
Year of manufacture	2015
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg
CO2 emission	195 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-07-16
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-09
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	32
Total items failed	12

MOT #9	2024-02-10 10:27
--------	------------------

MOT test number	678823819752
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2025-02-09
------------------	------------

- Minor

Nearside Front Windscreen damaged but not adversely affecting driver's view slight damage (3.2 (a) (i))
- Advice

Front Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))
- Advice

Rear Upper Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))
- Advice

Rear Tyre slightly damaged/cracking or perishing Both sides (5.2.3 (d) (ii))
- Minor

Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice

Rear Tyre worn close to legal limit/worn on edge inner and outer both sides (5.2.3 (e))
- Advice

Offside Front Indicator light plastic broken

**MOT #8**

2022-10-03 08:00

MOT test number

301456608759

Result

✓ Passed

Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**Advice** Central Front Shock absorbers has light misting of oil (5.3.2 (b))**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #7**

2021-03-23 15:38

MOT test number

885921572939

Result

✓ Passed

Advice Rear both rear bump stops in poor order**Advice** Offside mirror repeater cover missing**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #6**

2019-12-09 18:07

MOT test number

348461402837

Result

✓ Passed

Minor Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))**Advice** Nearside Front Brake pad wear wire broken**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Stop lamp(s) lens defective which has no effect on emitted light High level (4.3.1 (b) (i))

**MOT #5**

2019-12-09 11:04

MOT test number

646646718525

Result**✗ Failed**

- Fail** Nearside Front Service brake excessively binding (1.2.1 (f))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Nearside Front Brake pad wear wire broken
- Fail** Nearside Front Brakes imbalanced across an axle (1.2.1 (b) (i))
- Minor** Stop lamp(s) lens defective which has no effect on emitted light High level (4.3.1 (b) (i))

MOT #4

2018-12-10 12:36

MOT test number

796775083736

Result**✓ Passed**

- Advice** Red oil warning light active
- Advice** Front Both brake warning sensors wires broken

MOT #3

2018-12-10 11:49

MOT test number

265049633792

Result**✗ Failed**

- Advice** Red oil warning light active
- Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Front Both brake warning sensors wires broken
- Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



MOT #2	2017-12-29 14:24
MOT test number	101452907515
Result	✓ Passed
Advice	Nearside Rear Lamp damaged

MOT #1	2017-12-27 11:09
MOT test number	901602931872
Result	✗ Failed
Fail	Nearside Side repeater missing (1.4.A.2b)
Advice	Coolant level low
Fail	Nearside Body has a sharp edge caused by damage Wing mirror (6.1.C.1)
Fail	Nearside Rear Body has a projection caused by damage lamp (6.1.C.1)
Fail	Parking brake: efficiency below requirements (3.7.B.7)
Fail	Offside Obligatory mirror seriously damaged, affecting the rear view (8.1.2a)
Fail	Offside Side repeater missing (1.4.A.2b)
Fail	Offside Body has a projection caused by damage wing mirror (6.1.C.1)
Fail	Nearside Front rear parking brake recording little or no effort (3.7.B.6a)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
9 February 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	9 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-01-30
Last registration	2024-02-10
Complete history	See info



Registration #1	2015-01-30	28 mi
Registration #2	2017-12-27	61.353 mi
Registration #3	2017-12-29	61.430 mi
Registration #4	2018-12-10	82.021 mi
Registration #5	2018-12-10	82.021 mi
Registration #6	2019-12-09	98.349 mi
Registration #7	2019-12-09	98.349 mi
Registration #8	2019-12-09	98.349 mi
Registration #9	2019-12-09	98.349 mi
Registration #10	2019-12-09	98.349 mi
Registration #11	2019-12-09	98.349 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJA0875452