



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO SE TSI
Colour	Blue
Year of manufacture	2019
Top speed	116 mph
0 - 100 km/h	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 kW / 95 HP / 94 BHP
Max. torque	175 Nm at 2.000 rpm
Engine capacity	999 cc
Cylinders	3
Fuel type	Petrol
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	52.3 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 1

Date	2022-05-17
Pictures	1
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-04-09
MOT pass rate	75 %
MOT passed	3
Failed MOT tests	1
Total advice items	10
Total items failed	1

## MOT #4 2024-04-02 12:06

MOT test number 337264727313

Result ✓ Passed

Next expiry date 2025-04-09

**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. slight imbalance (1.2.1 (b) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Central Front Items removed from driver's view prior to test

**Advice** Offside Front Tyre worn close to legal limit/worn on edge just starting to get low (5.2.3 (e))

## MOT #3 2023-04-05 09:45

MOT test number 680595915383

Result ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Central Front Items removed from driver's view prior to test air freshener

## MOT #2 2022-04-01 11:38

MOT test number 213809000818

Result ✓ Passed

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))



MOT #1	2022-04-01 11:38
MOT test number	808536747242
Result	✗ Failed
Pass with rectification	Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
9 April 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	93
<b>MOT expiry date</b>	9 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 <b>GL19BXD</b>
Plate since	2019-03-29
Current registration	 <b>GL19BXD</b>
Plate since	2019-03-29

More info >





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-04-10
Last registration	2024-04-02
Complete history	<a href="#">See info</a>



Registration #1	2019-04-10	8 mi
Registration #2	2022-04-01	30.701 mi
Registration #3	2022-04-01	30.701 mi
Registration #4	2022-04-01	30.701 mi
Registration #5	2022-04-01	30.701 mi
Registration #6	2022-04-01	30.701 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	85%
Pedestrian	76%
Safety systems	59%
Overall rating	82%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1751 mm
Height	1461 mm
Length	4053 mm
Wheel base	2551 mm
Kerb weight	1070 kg
Max. allowed weight	1610 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	DKLA062185