



SN09NDF

report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Blue
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	279 Nm at 1.900 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	65.7 mpg
Consumption combined	54.3 mpg





Internet history

Entry 1

Date	2021-01-30
Pictures	9
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT #10	2020-08-27 17:24
MOT test number	207917390077
Result	✓ Passed
Next expiry date	2021-08-26
Advice	Front Drag link end ball joint has slight play Both Side (2.1.3 (b) (i))
Advice	Both Side Wings Slightly Corroded
Advice	Rear Tyre worn close to legal limit/worn on edge Both Side (5.2.3 (e))

MOT #9	2019-05-11 10:18
MOT test number	546470569435
Result	✓ Passed

MOT #8	2019-05-11 07:03
MOT test number	394455392525
Result	✗ Failed
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Exhaust shield missing where fitted as original equipment creating a risk of fire loose an insecure (6.1.3 (e))
Fail	Offside Front Service brake excessively binding (1.2.1 (f))
Fail	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Fail	Nearside Rear Anti-roll bar linkage missing (5.3.3 (a) (ii))



MOT #72018-05-01 14:45

MOT test number254172590261

Result	✓ Passed
<div><div>Advice</div><div>Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)</div></div>	
<div><div>Advice</div><div>Nearside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (5.2.6)</div></div>	
<div><div>Advice</div><div>Central Front Oil leak engine</div></div>	
<div><div>Advice</div><div>Offside Rear Inner Road wheel with a slightly distorted bead rim edge (4.2.A.1a)</div></div>	
<div><div>Advice</div><div>Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)</div></div>	
<div><div>Advice</div><div>Offside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill/wheelarch (5.2.6)</div></div>	
<div><div>Advice</div><div>Nearside Rear Inner Road wheel with a slightly distorted bead rim edge (4.2.A.1a)</div></div>	

**MOT #6**

2018-05-01 08:38

MOT test number

678955568106

Result

✗ Failed

Advice Nearside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill (5.2.6)

Fail Front Tyre has ply or cords exposed both n/s and o/s (4.1.D.1b)

Advice Central Front Oil leak engine

Fail Rear Exhaust system not adequately supported (7.1.1)

Advice Offside Rear Inner Road wheel with a slightly distorted bead rim edge (4.2.A.1a)

Advice Offside Rear Inner Suspension component mounting prescribed area is corroded but not considered excessive sill (2.4.A.3)

Fail Rear Registration plate lamp not working (1.1.C.1d)

Advice Offside Rear Outer Seat belt anchorage prescribed area is corroded but not considered excessive sill/wheelarch (5.2.6)

Fail Nearside Front Suspension arm rubber bush deteriorated resulting in excessive movement rear bush (2.4.G.2)

Advice Nearside Rear Inner Road wheel with a slightly distorted bead rim edge (4.2.A.1a)

MOT #5

2017-05-05 11:21

MOT test number

815404890100

Result

✓ Passed

MOT #4

2016-05-18 15:38

MOT test number

965914733027

Result

✓ Passed

MOT #3

2015-06-08 09:56

MOT test number

575199655190

Result

✓ Passed



MOT #2	2013-09-11 10:23
MOT test number	979124653220
Result	✓ Passed

MOT #1	2012-08-03 11:25
MOT test number	988026112232
Result	✓ Passed

- Notice

Front wiperblades slightly smearing screen
- Advice

Front Brake pad(s) wearing thin (3.5.1g)
- Notice

O/s/r tyre low tread on outer edges and different tread pattern from rest of tyres



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	SN09NDF
Plate since	2024-03-29
Current registration	SN09NDF
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2009-08-05
Last registration	2020-08-27
Complete history	See info



Registration #1	2009-08-05	11 mi
Registration #2	2012-08-03	43.688 mi
Registration #3	2013-09-11	60.187 mi
Registration #4	2015-06-08	83.348 mi
Registration #5	2016-05-18	95.032 mi
Registration #6	2017-05-05	103.744 mi
Registration #7	2018-05-05	111.777 mi
Registration #8	2019-05-05	119.810 mi
Registration #9	2020-05-05	127.843 mi
Registration #10	2021-05-05	135.876 mi
Registration #11	2022-05-05	143.909 mi
Registration #12	2023-05-05	151.942 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2019 mm
Height	1500 mm
Length	4337 mm
Wheel base	2640 mm
Kerb weight	1279 kg
Max. allowed weight	1950 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U56246