





report date: 2024-03-28

General information

Make	FORD
Model	GALAXY ZETEC TDCI (125PS)
Colour	Orange
Year of manufacture	-
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	285 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2021-12-16

Pictures 22

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

MOT #16 2021-05-17 14:14

MOT test number 398950890933

Result ✓ Passed

Next expiry date 2022-05-16

MOT #15 2021-05-13 13:32

MOT test number 196192383477

Result X Failed

Fail Offside Parking brake inoperative on one side (1.4.1 (a))

Fail Parking brake efficiency below requirements (1.4.2 (a) (i))

MOT #14 2020-03-18 16:23

MOT test number 982680658952

Result
✓ Passed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge perishing (5.2.3 (e))

MOT #13 2020-03-17 16:25

MOT test number 215089494707

Result × Failed

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge perishing (5.2.3 (e))

Fail Fuel system component leaking injector area (6.1.3 (b) (i))

MOT #12 2019-04-03 14:43

MOT test number 773268511912

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #11	2018-04-18 15:53
MOT test number	806011197603
Result	✓ Passed
MOT #10	2018-04-18 13:25
MOT test number	792589603225
Result	X Failed
Fail Nearside Front Steering rack gaiter split (2.2.D.2d)	
Fail Offside Rear Registration plate lamp not working (1.1.C.1d)	
Fail Offside Front Steering rack gaiter split (2.2.D.2d)	

MOT #9	2017-04-03 08:59
MOT test number	678009526276
Result	✓ Passed
MOT #8	2016-04-13 14:29
MOT test number	847258427256
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #7	2015-04-20 09:28
MOT test number	756960515185
Result	✓ Passed
MOT #6	2014-04-04 12:49
MOT test number	256574694082
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

MOT #5	2013-04-22 11:22
MOT test number	255342713402
Result	✓ Passed
Notice Passenger seat(s) missing at time of test	

MOT #4	2013-04-20 11:21	
MOT test number	136350713197	
Result	X Failed	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)		
Fail Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)		
Notice Passenger seat(s) missing at time of test		

MOT #3		2012-03-20 09:30
MOT test number		899000782036
Result		✓ Passed
MOT #2		2011-03-05 09:23
MOT test number		515644161052
Result		✓ Passed
MOT #1		2011-03-05 09:23
MOT test number		798894161094
Result		X Failed
Pass with rectification	Rear Direction indicators incorrect colour (1.4.A.2f)	

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

\sim		L :	~+~	
UV	ner	ш	SIC	ш

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report by	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Current registration	UK JIN
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-03-27
Last registration	2021-05-17
Complete history	See info



Registration #1	2008-03-27	15 mi
Registration #2	2011-03-05	15.684 mi
Registration #3	2012-03-20	26.323 mi
Registration #4	2013-04-20	43.851 mi
Registration #5	2013-04-22	43.851 mi
Registration #6	2014-04-04	54.540 mi
Registration #7	2015-04-20	62.340 mi
Registration #8	2016-04-13	68.696 mi
Registration #9	2017-04-03	77.919 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91.777 es
Registration #16		11.777 es
Registration #17		D.277 es

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/11



MV08NHC report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
60566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1807 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 11/11