





### General information

Make	VAUXHALL
Model	MOVANO F3500 L3H1 C/C CDTI
Colour	White
Year of manufacture	2013
Top speed	90 mph
0 - 60 mph	14.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	123 BHP
Max. torque	310 Nm at 2.500 rpm
Engine capacity	2.299 сс
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	37.7 mpg
Consumption combined	34.4 mpg
CO2 emission	209 g/km
CO2 label	К





FV63ORK report date: 2024-03-29

Internet history			
Entry 1			
Date	2021-09-0	)1	
Pictures	9		
Listing price	View repo	<u>rt</u>	
Like me? Finance me	Video viewing with one of our team.   Book a video viewing with one of our team.   Witter examine terms them.	Van NOW,   VAT Later   No deposit required until your 3 <sup>st</sup> payment   MODE NOW   MODE NOW   MODE NOW	Cick & Deliver   Cick & Deliver   Complete your deal online or by phone.   The arrange for the cantened while it his dedivated to not.   Cick are welches terreservelter

source: cargurus.co.uk



# MOT history

MOT expiry date	2023-10-05
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	8
Total items failed	8

MOT #10	2022-10-06 14:09
MOT test number	467627518930
Result	✓ Passed
Next expiry date	2023-10-05
Advice UNDER COVERS FITTED NOT ALLOWING FULL INSPECTION OF THE UNDERSIDE ARE	ĒA

MOT #9	2021-09-21 09:33
MOT test number	790399954012
Result	✓ Passed

MOT #8	2021-09-13 13:44
MOT test number	432251866948
Result	🗙 Failed
<b>Fail</b> Nearside Tyre has ply or cords exposed both (5.2.3 (d) (ii))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	
<b>Fail</b> Front Brake pipe excessively corroded both (1.1.11 (c))	

MOT #7		2020-09-25 12:56
MOT test i	number	697064242505
Result		🗸 Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)	)





MOT #6	2020-09-25 09:25
MOT test number	842254356410
Result	🗙 Failed
Fail Nearside Side repeater not working (4.4.1 (a) (ii))	
Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (	c))
<b>Fail</b> Side repeater lens defective such that the emitted light is adversely affected (4.4.1	. (b) (ii))

MOT #5	2019-04-04 14:30
MOT test number	290115972682
Result	✓ Passed

MOT #4	2018-04-03 12:43
MOT test number	457975216446
Result	✓ Passed

MOT #3	2018-03-29 15:41
MOT test number	706489694841
Result	🗙 Failed
Advice Offside Front Tyre worn close to the legal limit almost to cords on inner edge (4	4.1.E.1)
<b>Fail</b> Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)	

MOT #2		2016-11-03 12:07
MOT test	number	225736883925
Result		✓ Passed
Advice	Brake pad(s) wearing thin all (3.5.1g)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	





MOT #1	2016-11-02 10:59	
MOT test number	202707910992	
Result	🗙 Failed	
Fail   Rear Leaf spring to axle securing bolt insecure both anchor bolts (2.4.B.7b)		
Advice Brake pad(s) wearing thin all (3.5.1g)		
<b>Fail</b> Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)		
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		



Tax & MOT check

✓ Taxed	Х МОТ
Tax due: 1 October 2024	Expired: 5 October 2023
Tax status	Valid until 1 October
Days left	155
MOT expiry date	5 October 2023
Full MOT history	See MOT history

## Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-





### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FET A
Category	L AMP
Туре	
Damage 2	AMPLE
Date	4
Category	AMPL
Туре	

#### Extra VAUXHALL salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.00.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





### Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

**********	
ACCOUNTS AND A DESCRIPTION OF A DESCRIPR	
And and a second s	
**********	
********	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2013-11-06
Last registration	2022-10-06
Complete history	See info



Registration #1	2013-11-06	9 mi
Registration #2	2016-11-02	32.926 mi
Registration #3	2016-11-03	32.928 mi
Registration #4	2018-03-29	45.614 mi
Registration #5	2018-04-03	45.615 mi
Registration #6	2019-04-04	53.294 mi
Registration #7		11.227 mi
Registration #8		11.777 mi
Registration #8 Registration #9		11.577 est 11.577 est
		01.000 est 01.000 est 01.000 est
Registration #9		01.000 est 01.000 est 01.000 est 01.000 est

More info >





# Safety ratings

NCAP rating	****
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	see crash video



Dimensions & weight	
Width	2470 mm
Height	2284 mm
Length	6293 mm
Kerb weight	1707 kg
Max. allowed weight	3500 kg
Additional information	
Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Engine number	M9T -C052629 LWL