



HYUNDAI



report date: 2024-03-28

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Silver
Year of manufacture	2005
Top speed	93 mph
0 - 60 mph	16.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	62 BHP
Max. torque	94 Nm at 3.200 rpm
Engine capacity	1.086 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	48.7 mpg
CO2 emission	133 g/km
CO2 label	E





MOT history

MOT expiry date	2021-11-29
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	31
Total items failed	8

MOT #172020-11-10 15:52

MOT test number401410996385

Result✓ Passed

Next expiry date2021-11-29

- AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))
- AdviceExhaust has a minor leak of exhaust gases (6.1.2 (a))
- AdviceRear box baffles coming out of box
- AdviceOffside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceCentre stop lamp not working
- AdviceSquealing noise - auxiliary area

**MOT #16**

2020-11-10 09:53

MOT test number

121646933359

Result**✗ Failed**

- Advice** Squealing noise - auxiliary area
- Fail** Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Rear box baffles coming out of box
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Centre stop lamp not working

MOT #15

2019-05-30 15:43

MOT test number

181024528555

Result**✓ Passed**

- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material minor corrosion across rear axle and where retained in clips (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material across axle corrosion (1.1.11 (c))

**MOT #14** 2019-05-30 10:02**MOT test number** 315130231760**Result** ✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Rear Brake pipe excessively corroded flexi to hub (1.1.11 (c))

Advice Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))

Fail Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material across axle corrosion (1.1.11 (c))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material minor corrosion across rear axle and where retained in clips (1.1.11 (c))

MOT #13 2018-05-02 14:04**MOT test number** 321833000149**Result** ✓ Passed**MOT #12** 2018-04-18 09:53**MOT test number** 420532875077**Result** ✗ Failed

Fail Front Sub-frame corroded and seriously weakened (2.4.G.1)

MOT #11 2017-04-03 12:07**MOT test number** 929401882540**Result** ✓ Passed**MOT #10** 2016-05-12 14:16**MOT test number** 312118882301**Result** ✓ Passed

**MOT #9** 2016-05-12 10:57**MOT test number** 586667056395**Result** ✗ Failed**Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)**Advice** High level brake light not working**MOT #8** 2015-05-13 10:55**MOT test number** 999503735152**Result** ✓ Passed**MOT #7** 2014-05-19 09:59**MOT test number** 677279834197**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear registration plate deteriorated but not likely to be misread (6.3.1d)**MOT #6** 2013-05-07 10:37**MOT test number** 616197523158**Result** ✓ Passed**Notice** Offside front tyre worn on edges**Notice** Edges worn on rear tyres**Notice** Nearside front tyre worn on edges and small damage to outer sidewall**Notice** Small cuts in offside front tyre tread**Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)



MOT #5	2012-05-10 10:17
MOT test number	207181632404
Result	✓ Passed
Advice	Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #4	2011-05-04 13:35
MOT test number	887894521145
Result	✓ Passed

MOT #3	2010-05-11 12:04
MOT test number	933731730196
Result	✓ Passed

MOT #2	2009-05-18 12:01
MOT test number	914138739182
Result	✓ Passed

MOT #1	2008-05-20 13:59
MOT test number	274861848440
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
15 January 2021

✕
MOT

Expired:
29 November 2021

Tax status	Expired at 15 January 2021
Days left	1200 days too late
MOT expiry date	29 November 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	BJ05ZYE
Plate since	2019-09-28
Current registration	BJ05ZYE
Plate since	2019-09-28

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2005-05-25
Last registration	2020-11-10
Complete history	See info



Registration #1	2005-05-25	6 mi
Registration #2	2008-05-20	19.552 mi
Registration #3	2009-05-18	23.997 mi
Registration #4	2010-05-11	30.042 mi
Registration #5	2011-05-04	36.798 mi
Registration #6	2012-05-10	43.216 mi
Registration #7	2013-05-07	47.477 mi
Registration #8	2014-05-19	50.922 mi
Registration #9	2015-05-13	54.323 mi
Registration #10	2016-05-20	58.377 mi
Registration #11	2017-05-20	62.377 mi
Registration #12	2018-05-20	66.377 mi
Registration #13	2019-05-20	70.377 mi
Registration #14	2020-05-20	74.377 mi
Registration #15	2021-05-20	78.377 mi
Registration #16	2022-05-20	82.377 mi
Registration #17	2023-05-20	86.377 mi
Registration #18	2024-05-20	90.377 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3810 mm
Wheel base	2455 mm
Kerb weight	998 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Number of axles	2
Engine number	G4HD4E32703