




report date: 2025-02-13

General information

Make	FIAT
Model	MAREA 115 16V HLX
Colour	Blue
Year of manufacture	-
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	111 BHP
Max. torque	154 Nm at 4.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	43.5 mpg
Consumption combined	34.0 mpg





Internet history

Entry 1

Date	2021-12-09
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #20	2022-09-06 14:29
MOT test number	287237563144
Result	✗ Failed
MAJOR Offside Seat belt anchorage prescribed area strength or continuity significantly reduced FLOOR (7.1.1 (a) (i))	
DANGEROUS Fuel tank leaking excessively or a risk of fire (6.1.3 (b) (ii))	
MAJOR Headlamp not working on main beam (4.1.1 (a) (ii))	
DANGEROUS Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
MAJOR Central Exhaust silencer insecure (8.1.1 (b) (i))	
MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced SILL/FLOOR (7.1.1 (a) (i))	
MAJOR Fuel pipe union leaking ENGINE BAY (6.1.3 (b) (i))	
DANGEROUS Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Nearside Rear Position lamp not working (4.2.1 (a) (ii))	

MOT #19	2021-09-06 17:12
MOT test number	202521711746
Result	✓ Passed

MOT #18	2021-09-06 11:03
MOT test number	250201934910
Result	✗ Failed
MAJOR Rear Seat belt anchorage prescribed area is inadequately repaired (7.1.1 (a) (i))	
MAJOR Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))	
MAJOR Nearside Seat belt anchorage prescribed area strength or continuity significantly reduced SILL (7.1.1 (a) (i))	



MOT #17 2020-09-10 11:58

MOT test number 814201314246

Result ✔ Passed

MOT #16 2020-09-10 11:58

MOT test number 537985337648

Result ✘ Failed

Pass with rectification Offside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

Pass with rectification Nearside Rear Brake hose excessively deteriorated (1.1.12 (b) (ii))

MOT #15 2019-09-23 10:26

MOT test number 797810485566

Result ✔ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Front Brake pipe corroded, covered in grease or other material to rear at rear (1.1.11 (c))

Advice Coil spring corroded all (5.3.1 (b) (i))

Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Front Brake pipe corroded, covered in grease or other material to rear at rear (1.1.11 (c))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #14 2018-09-25 09:13

MOT test number 508542102872

Result ✔ Passed

MOT #13 2017-09-29 09:51

MOT test number 788211930607

Result ✔ Passed



MOT #12 2016-08-26 09:50

MOT test number 603937523167

Result ✓ Passed

MOT #11 2015-09-02 10:01

MOT test number 788744379085

Result ✓ Passed

MOT #10 2015-09-02 10:01

MOT test number 936814064748

Result ✗ Failed

Pass with rectification Nearside Suspension component mounting prescribed area is excessively corroded (2.4.A.3)

MOT #9 2014-08-20 11:00

MOT test number 438342634225

Result ✓ Passed

MOT #8 2013-08-28 18:57

MOT test number 396570043416

Result ✓ Passed

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #7 2012-08-24 16:20

MOT test number 475227332281

Result ✓ Passed

MOT #6 2011-09-06 10:47

MOT test number 435759941205

Result ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #5	2010-09-08 11:06
MOT test number	241771850258
Result	✓ Passed
Advice	Offside Steering rack damaged but serviceable (2.2.C.1d)

MOT #4	2009-08-25 11:17
MOT test number	173427239295
Result	✓ Passed
Notice	Suspension joint offside lower dust cover split/missing

MOT #3	2008-08-28 15:39
MOT test number	980821948294
Result	✓ Passed

MOT #2	2007-09-13 10:29
MOT test number	990846057297
Result	✓ Passed

MOT #1	2006-09-06 13:40
MOT test number	250229046268
Result	✓ Passed




Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



Damage 2

Date	EXAMPLE
Category	EXAMPLE
Type	EXAMPLE



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	X989EEU
Plate since	2019-09-29
Current registration	X989EEU
Plate since	2019-09-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2000-09-25
Last registration	2022-09-06
Complete history	See info



Registration #1	2000-09-25	29 mi
Registration #2	2006-09-06	32.860 mi
Registration #3	2007-09-13	37.237 mi
Registration #4	2008-08-28	40.120 mi
Registration #5	2009-08-25	44.058 mi
Registration #6	2010-09-08	47.207 mi
Registration #7	2011-09-06	50.538 mi
Registration #8	2012-08-24	53.402 mi
Registration #9	2013-08-28	56.173 mi
Registration #10	2014-08-20	60.795 mi
Registration #11	2015-09-02	65.565 mi
Registration #12	2016-09-06	70.335 mi
Registration #13	2017-09-06	75.105 mi
Registration #14	2018-09-06	79.875 mi
Registration #15	2019-09-06	84.645 mi
Registration #16	2020-09-06	89.415 mi
Registration #17	2021-09-06	94.185 mi
Registration #18	2022-09-06	98.955 mi
Registration #19	2023-09-06	103.725 mi
Registration #20	2024-09-06	108.495 mi
Registration #21	2025-09-06	113.265 mi
Registration #22	2026-09-06	118.035 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1755 mm
Height	1420 mm
Length	4031 mm
Wheel base	2540 mm
Kerb weight	1100 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of axles	2
Engine number	1624146