





report date: 2024-03-29

General information

Make	NISSAN
Model	LEAF TEKNA
Colour	White
Year of manufacture	2015
Top speed	87 mph
0 - 60 mph	11.5 seconds
Gearbox	1 speed automatic

Engine & fuel consumption

Power	107 BHP
Max. torque	254 Nm at 10.500 rpm
Fuel type	Electricity



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2021-08-18

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



FM15FPG report date: 2024-03-29

MOT history

MOT expiry date	2024-08-16
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	13
Total items failed	0

MOT #7		2023-08-17 12:21
MOT test	number	657601983616
Result		✓ Passed
Next expi	ry date	2024-08-16
Advice	Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #6	2022-08-13 09:54
MOT test number	787935209062
Result	✓ Passed
MOT #5	2021-08-16 13:24
MOT test number	887725025992
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

491226232959

Result

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2020-10-19 11:45 **MOT** test number 315797215998 Result × Failed **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **MAJOR** Rear Rear fog lamp not working (4.5.1 (a) (ii)) Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords **MAJOR** 215/50 17 (5 2 3 (d) (i))

213/30 17 (3.2.3 (d) (l))	
MOT #2	2019-10-16 15:50
MOT test number	484449784213
Result	✓ Passed
MOT #1	2018-10-22 09:25
MOT test number	929766559224
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Days left 124

MOT expiry date 16 August 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim	MID.	~ r	hi	cti	200
יטי	wn	er.	ш	SU	ע וכ

For how long did the current and previous owner(s) have this NISSAN? How many owners have? Check it in the premium report and see all owner registrations. Download the full r		
nave: Check it in the premium report and see an owner registrations. Download the full r	eport <u>nere</u> .	

	More info >	
Plate changes		
See in this check if this NISSAN had different number plates.		
Number of plates		9
Current registration	NE OK	
Plate since	UN C	
Current registration	NK NA	
Plate since		
	More info >	

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2015-06-30
Last registration	2023-08-17
Complete history	See info



.	2015 06 20	22
Registration #1	2015-06-30	22 mi
Registration #2	2018-10-22	22.791 mi
Registration #3	2019-10-16	26.080 mi
Registration #4	2020-10-19	27.784 mi
Registration #5	2020-10-20	27.784 mi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		D.327 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	83%
Pedestrian	65%
Safety systems	84%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1550 mm
Length	4445 mm
Wheel base	2700 mm
Kerb weight	1525 kg
Max. allowed weight	1945 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 11/11