



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	E E220 CDI ELEGANCE
Colour	Silver
Year of manufacture	2008
Top speed	140 mph
0 - 60 mph	8.6 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.0 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.2 mpg
CO2 emission	174 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-03
Pictures	44
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-01
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	11
Total items failed	9

MOT #15	2023-05-27 10:56
MOT test number	567314807568
Result	✓ Passed
Next expiry date	2024-06-01

MOT #14	2022-05-27 09:41
MOT test number	660238626151
Result	✓ Passed
Minor	Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated REAR (5.3.4 (b) (i))
Advice	Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #13	2021-06-02 15:05
MOT test number	294731612186
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2020-11-25 18:11
MOT test number	803743337033
Result	✓ Passed

**MOT #11** 2020-11-24 14:17**MOT test number** 660109534464**Result** ✗ Failed

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Rear Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Front Brake lining(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #10 2019-11-23 14:31**MOT test number** 236182952637**Result** ✓ Passed**MOT #9** 2019-11-22 14:33**MOT test number** 379342787660**Result** ✗ Failed

- Fail** Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MOT #8 2018-12-03 11:37**MOT test number** 413250859405**Result** ✓ Passed**MOT #7** 2017-11-22 13:11**MOT test number** 949317006717**Result** ✓ Passed

**MOT #6** 2016-11-18 15:12**MOT test number** 174290979945**Result** ✓ Passed**Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** N/s/f tyre worn on inside edge on the limit,o/s/f tyre worn smooth inside edge**Advice** Under trays fitted**MOT #5** 2015-11-13 12:02**MOT test number** 980992309731**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Undertrays fitted**MOT #4** 2014-11-14 11:45**MOT test number** 116638414330**Result** ✓ Passed**MOT #3** 2013-11-08 11:52**MOT test number** 779332113347**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2012-11-15 12:24**MOT test number** 447180322382**Result** ✓ Passed



MOT #1	2011-11-21 12:35
MOT test number	938215821351
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
1 June 2024

Tax status	Valid until 1 June
Days left	34
MOT expiry date	1 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 BT08KCG
Plate since	2019-06-29
Current registration	 BT08KCG
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-05-28
Last registration	2023-05-27
Complete history	See info



Registration #1	2008-05-28	15 mi
Registration #2	2011-11-21	33.168 mi
Registration #3	2012-11-15	42.171 mi
Registration #4	2013-11-08	53.649 mi
Registration #5	2014-11-14	66.633 mi
Registration #6	2015-11-13	77.341 mi
Registration #7	2016-11-18	85.460 mi
Registration #8	2017-11-22	95.555 mi
Registration #9	2018-12-03	106.473 mi
Registration #10	2019-05-29	115.277 mi
Registration #11	2019-05-29	115.277 mi
Registration #12	2019-05-29	115.277 mi
Registration #13	2019-05-29	115.277 mi
Registration #14	2019-05-29	115.277 mi
Registration #15	2019-05-29	115.277 mi
Registration #16	2019-05-29	115.277 mi
Registration #17	2019-05-29	115.277 mi

More info >



Dimensions & weight

Width	1822 mm
Height	1483 mm
Length	4852 mm
Wheel base	2833 mm
Kerb weight	1785 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64682130238396