



report date: 2024-03-28

General information

|                     |                |
|---------------------|----------------|
| Make                | AUDI           |
| Model               | A2 TDI SE      |
| Colour              | Black          |
| Year of manufacture | 2003           |
| Top speed           | 107 mph        |
| 0 - 60 mph          | 12.3 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 74 BHP              |
| Max. torque             | 195 Nm at 2.200 rpm |
| Engine capacity         | 1.390 cc            |
| Cylinders               | 3                   |
| Fuel type               | Diesel              |
| Consumption city        | 50.4 mpg            |
| Consumption extra urban | 80.7 mpg            |
| Consumption combined    | 65.7 mpg            |
| CO2 emission            | 119 g/km            |
| CO2 label               | C                   |





Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-07-01                  |
| Pictures      | 12                          |
| Listing price | <a href="#">View report</a> |



source: [autotrader.co.uk](#)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-05 |
| MOT pass rate      | 79 %       |
| MOT passed         | 19         |
| Failed MOT tests   | 5          |
| Total advice items | 23         |
| Total items failed | 13         |

|                  |                  |
|------------------|------------------|
| MOT #24          | 2024-02-05 09:28 |
| MOT test number  | 974708716557     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-02-05       |

|   |                  |
|---|------------------|
| MOT #23   | 2024-02-01 15:57 |
| MOT test number   | 880875156978     |
| Result  | ✗ Failed         |
| <b>MAJOR</b> Registration plate lamp inoperative in the case of a single lamp or all lamps both rear (4.7.1 (b) (ii)) |                  |

|  |                  |
|--|------------------|
| MOT #22  | 2023-02-01 09:00 |
| MOT test number  | 298695423716     |
| Result   | ✓ Passed         |
| <b>Advice</b> Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii)) |                  |
| <b>Advice</b> Oil leak, but not excessive (8.4.1 (a) (i))  |                  |

**MOT #21** 2022-01-21 09:53**MOT test number** 175782380654**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened both front (1.1.14 (a) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #20** 2021-01-27 08:13**MOT test number** 408981452197**Result** ✓ Passed**MOT #19** 2021-01-25 09:34**MOT test number** 563098160259**Result** ✗ Failed**MAJOR** Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))**MAJOR** Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #18** 2020-02-06 09:11**MOT test number** 671276631865**Result** ✓ Passed**Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #17** 2018-11-01 08:54**MOT test number** 828107773195**Result** ✓ Passed**Advice** Nearside Rear nail in tyre

**MOT #16** 2017-10-26 09:03**MOT test number** 233447325038**Result** ✓ Passed**MOT #15** 2017-10-23 08:19**MOT test number** 885013497641**Result** ✗ Failed**Fail** Nearside Front Road wheel bead rim badly distorted Inner rim (4.2.A.1a)**Fail** Nearside Front Brake hose excessively deteriorated (3.6.B.4d)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Brake hose slightly deteriorated (3.6.B.4d)**Fail** Offside Rear Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Headlamp not working on main beam (1.7.5a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #14** 2016-11-17 13:01**MOT test number** 581911257777**Result** ✓ Passed**Advice** Front discs slightly corroded on inner edges**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front pads will need replacing in the near future

**MOT #13** 2016-11-15 09:22**MOT test number** 471348891520**Result** ✗ Failed**Advice** Front discs slightly corroded on inner edges**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front pads will need replacing in the near future**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12** 2016-01-05 12:04**MOT test number** 845992067486**Result** ✓ Passed**Advice** Nsr nail in tread**MOT #11** 2015-01-30 11:36**MOT test number** 597540635073**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #10** 2014-01-27 17:40**MOT test number** 545037124063**Result** ✓ Passed

**MOT #9** 2014-01-22 14:07**MOT test number** 825572924095**Result** ✗ Failed

**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

**Fail** Offside Front coil spring broken (2.4.C.1a)

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside rear brake binding (3.7.B.1)

**Fail** Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2013-01-02 14:37**MOT test number** 228542903016**Result** ✓ Passed**MOT #7** 2012-01-05 09:56**MOT test number** 136325502483**Result** ✓ Passed**MOT #6** 2011-01-31 11:11**MOT test number** 957721831052**Result** ✓ Passed

**Notice** Front brake pads showing signs of wear

**MOT #5** 2010-01-13 15:40**MOT test number** 180163910063**Result** ✓ Passed



|                 |  |
|-----------------|--|
| MOT #4          | 2009-01-10 11:43   |
| MOT test number | 490200919091   |
| Result          | ✓ Passed   |
| MOT #3          | 2008-01-24 15:13   |
| MOT test number | 862864728078   |
| Result          | ✓ Passed   |
| Advice          | Offside Rear Direction indicator slightly discoloured (1.4.A.2f) |
| MOT #2          | 2007-03-08 09:52   |
| MOT test number | 682517567029   |
| Result          | ✓ Passed   |
| MOT #1          | 2006-03-15 11:15   |
| MOT test number | 342734576009   |
| Result          | ✓ Passed   |





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
5 February 2025

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 July              |
| <b>Days left</b>        | 62                              |
| <b>MOT expiry date</b>  | 5 February 2025                 |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |                |
|--|----------------|
| <b>Vehicle class</b>                           | 49             |
| <b>Band</b>                                    | C              |
| <b>Single payment (12 months)</b>              | £ 35,00,-      |
| <b>Single six month payment</b>                | Not applicable |
| <b>Total payable by 12 monthly instalments</b> | £ 36,75,-      |




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this AUDI had different number plates.

|                      |               |
|----------------------|---------------|
| Number of plates     | 1             |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |
| Current registration | <b>XXXXXX</b> |
| Plate since          | 2024-03-28    |

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

|                   |            |      |
|-------------------|------------|------|
| Finance company   | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type    | XXXXXXXXXX | XXXX |
| Agreement term    | XXXXXXXXXX | XXXX |
| Agreement number  | XXXXXXXXXX | XXXX |
| Contact info      | XXXXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 26                       |
| First mileage registration | 2003-03-25               |
| Last registration          | 2024-02-05               |
| Complete history           | <a href="#">See info</a> |



|                  |            |           |
|------------------|------------|-----------|
| Registration #1  | 2003-03-25 | 14 mi     |
| Registration #2  | 2006-03-15 | 16.869 mi |
| Registration #3  | 2007-03-08 | 21.248 mi |
| Registration #4  | 2008-01-24 | 26.004 mi |
| Registration #5  | 2009-01-10 | 40.478 mi |
| Registration #6  | 2010-01-13 | 49.789 mi |
| Registration #7  | 2011-01-31 | 56.012 mi |
| Registration #8  | 2012-01-05 | 62.519 mi |
| Registration #9  | 2013-01-02 | 71.611 mi |
| Registration #10 | 2014-01-22 | 78.474 mi |
| Registration #11 | 2014-01-27 | 78.474 mi |
| Registration #12 | 2015-01-30 | 88.266 mi |
| Registration #13 | 2016-01-05 | 95.827 mi |
| Registration #14 | 2016-01-05 | 95.827 mi |
| Registration #15 | 2016-01-05 | 95.827 mi |
| Registration #16 | 2016-01-05 | 95.827 mi |
| Registration #17 | 2016-01-05 | 95.827 mi |
| Registration #18 | 2016-01-05 | 95.827 mi |
| Registration #19 | 2016-01-05 | 95.827 mi |
| Registration #20 | 2016-01-05 | 95.827 mi |
| Registration #21 | 2016-01-05 | 95.827 mi |
| Registration #22 | 2016-01-05 | 95.827 mi |
| Registration #23 | 2016-01-05 | 95.827 mi |
| Registration #24 | 2016-01-05 | 95.827 mi |
| Registration #25 | 2016-01-05 | 95.827 mi |
| Registration #26 | 2016-01-05 | 95.827 mi |

**More info** >



Car features

The AUDI factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 1676 mm |
| Height      | 1550 mm |
| Length      | 3810 mm |
| Wheel base  | 2405 mm |
| Kerb weight | 990 kg  |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 34 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of axles    | 2                |
| Engine number      | AMF 259401       |