





report date: 2024-03-29

General information

Make	AUDI
Model	A6 SE
Colour	Grey
Year of manufacture	2006
Top speed	137 mph
0 - 60 mph	9.5 seconds
Gearbox	7 speed CVT

Engine & fuel consumption

Power	174 BHP
Max. torque	230 Nm at 3.000 rpm
Engine capacity	2.393 сс
Cylinders	6
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	29.4 mpg
CO2 emission	238 g/km
CO2 label	L



CarCheck.co.uk page 1/13



Internet history

Entry 1

Date 2021-05-23


Pictures 21

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2024-11-22
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	28
Total items failed	0

MOT #16	2023-11-21 13:55
MOT test number	351038239534
Result	✓ Passed
Next expiry date	2024-11-22
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Minor Offside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))	
Advice Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	
Minor Nearside Front Inner Drive shaft joint constant velocity boot severely deterior	prated (6.1.7 (g) (i))

MOT #15		2022-11-21 12:46
MOT test	number	476809931573
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))	
Advice	Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))	

MOT #14	2021-11-23 13:56
MOT test number	762636137061
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #13		2020-11-04 09:41
MOT test number	er	384403191180
Result		✓ Passed
Advice Both	Rear Tyres Out Of Shape	
Advice Nears	side Rear Nail in tyre	

MOT #12		2019-11-14 14:28
MOT test	number	232649430449
Result		✓ Passed
Advice	Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #11		2018-11-09 11:39
MOT test	number	733843004754
Result		✓ Passed
MOT #10		2018-11-07 11:42
MOT test	number	940931540436
Result		× Failed
MAJOR	Offside Parking brake inoperative on one side (1.4.1 (a))	

MOT #9	2017-11-10 09:59
MOT test number	296782761651
Result	✓ Passed
Advice Under-trays fitted obscuring some underside components	

CarCheck.co.uk page 4/13



Advice

Advice

Nail in nearside rear tyre

Offside Front Tyre worn close to the legal limit (4.1.E.1)

AJ06AEC

report date: 2024-03-29

MOT #8 2016-11-09 11:50 886540678626 **MOT** test number Result ✓ Passed **MOT #7** 2015-11-10 08:08 **MOT** test number 344007091048 Result ✓ Passed Under-trays fitted obscuring some underside components **Advice** Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6

MOT test number

669408914335

Result

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT test number

466314452335

Advice | Child seat fitted not allowing full inspection of adult belt

Advice | Rear Brake pad(s) wearing thin (3.5.1g)

Advice | Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

CarCheck.co.uk page 5/13



MOT #4

MOT test number

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Child seat fitted not allowing full inspection of adult belt

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

2010-08-13 17:26 **MOT #3 MOT** test number 303055520209 Result ✓ Passed **MOT #2** 2010-04-22 12:14 813472310133 **MOT** test number Result ✓ Passed 2009-04-04 12:30 **MOT #1 MOT test number** 413594699066 Result ✓ Passed **Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1) **Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner	hictor,
UWNEI	nisioiv

For how long did the current and previous owner(s) have this AUDI? How many owners did check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-04-26
Last registration	2023-11-21
Complete history	See info



Registration #1	2006-04-26	20 mi
Registration #2	2009-04-04	22.576 mi
Registration #3	2010-04-22	32.832 mi
Registration #4	2010-08-13	35.357 mi
Registration #5	2011-12-13	44.181 mi
Registration #6	2012-12-19	52.333 mi
Registration #7	2014-11-14	62.160 mi
Registration #8	2015-11-10	69.600 mi
Registration #9	2016-11-09	75.225 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 aug

More info >

page 12/13 CarCheck.co.uk



Car features

50225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1855 mm
Height	1463 mm
Length	4933 mm
Wheel base	2843 mm
Kerb weight	1625 kg
Max. allowed weight	2255 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Multi-Point Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13