





report date: 2024-03-28

General information

Make	VOLVO
Model	S90 D4 INSCRIPTION
Colour	Black
Year of manufacture	2016
Top speed	140 mph
0 - 60 mph	7.9 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	190 BHP
Max. torque	400 Nm at 2.500 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	72.4 mpg
Consumption combined	64.2 mpg
CO2 emission	116 g/km
CO2 label	С



CarCheck.co.uk page 1/11



Internet history

Entry 2

Date 2021-10-21

Pictures 41

Listing price <u>View report</u>









source: autotrader.co.uk


Entry 1

Date 2021-09-10

Pictures 4

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



B 4	\sim	- 1				
Μ	()	1	าเ	ST	'n	rv

MOT expiry date	2024-10-05
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	14
Total items failed	1

MOT #6	2023-10-05 11:34
MOT test number	421139189716
Result	√ Passed
Next expiry date	2024-10-05

MOT #5	2022-09-30 08:26
MOT test number	880417951292
Result	✓ Passed
Advice Nearside Front Brake pad(s) we	aring thin (1.1.13 (a) (ii))
Advice Offside Front Brake pad(s) wear	ring thin (1.1.13 (a) (ii))

MOT #4	2021-10-06 03:38
MOT test number	297544246267
Result	✓ Passed

CarCheck.co.uk page 3/11



MOT #3 2020-08-27 12:44

MOT test number 590866684093

Advice Nearside Rear Tyre slightly damaged/cracking or perishing also getting close to the legal limit (5.2.3 (d) (ii))

Advice Exhaust emissions are too clean to get a reading

Advice Engine covers, under trays sill covers are fitted thus not allowing full inspection

Advice Offside Rear Tyre slightly damaged/cracking or perishing also getting close to the legal limit (5.2.3 (d) (ii))

Advice Offside rear lights is cracked but the operation of it is not affected

MOT #2 2020-08-27 12:44

MOT test number 598351550483

Result × Failed

Advice Exhaust emissions are too clean to get a reading

Advice Offside Rear Tyre slightly damaged/cracking or perishing also getting close to the legal limit (5.2.3 (d) (ii))

Advice Engine covers, under trays sill covers are fitted thus not allowing full inspection

Pass with rectification Offside Front Headlamp aim too high (4.1.2 (a))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing also getting close to the legal limit (5.2.3 (d) (ii))

Advice Offside rear lights is cracked but the operation of it is not affected

MOT #1 2019-08-29 14:26

MOT test number 502890290225

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge 255/35r20 (5.2.3 (e))

CarCheck.co.uk page 4/11



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	5 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 5/11



S90VLV

report date: 2024-03-28

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



factor scincore

S90VLV

report date: 2024-03-28

Owner history For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report here. More info > Plate changes See in this check if this VOLVO had different number plates.

More info >

CarCheck.co.uk page 8/11



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at Info	

Contact info

More info >

CarCheck.co.uk page 9/11



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-09-02
Last registration	2023-10-05
Complete history	See info



Registration #1	2016-09-02	20 mi
Registration #2	2019-08-29	38.177 mi
Registration #3	2020-08-27	52.948 mi
Registration #4	2020-08-27	52.948 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

50225	Air conditionin
50295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2019 mm
Height	1443 mm
Length	4963 mm
Wheel base	2941 mm
Kerb weight	1680 kg
Max. allowed weight	2270 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats CarCheck.co.uk	5 page 11/11