





report date: 2024-03-29

General information

| Make | LAND ROVER | |
|---------------------|-------------------------------|--|
| Model | DISCOVERY SPORT TD4 HSE BLACK | |
| Colour | Silver | |
| Year of manufacture | 2018 | |
| Top speed | 117 mph | |
| 0 - 100 km/h | 8.9 seconds | |
| 0 - 60 mph | 8.4 seconds | |
| Gearbox | 9 speed automatic | |

Engine & fuel consumption

| Power | 132 kW / 180 HP / 180 BHP |
|-------------------------|---------------------------|
| Max. torque | 430 Nm at 1.750 rpm |
| Engine capacity | 1.999 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 44.8 mpg |
| Consumption extra urban | 60.1 mpg |
| Consumption combined | 53.3 mpg |
| CO2 emission | 139 g/km |
| CO2 label | Е |



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-19


Pictures 25

Listing price <u>View report</u>









source: heycar.co.uk

CarCheck.co.uk page 2/11



OV18EFO report date: 2024-03-29

MOT history

| MOT expiry date | 2025-04-10 |
|--------------------|------------|
| MOT pass rate | 80 % |
| MOT passed | 4 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 1 |

| MOT #5 | 2024-04-10 13:54 |
|-----------------------------------|------------------|
| MOT test number | 582395254807 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-10 |
| Advice Nearside Rear Nail in tyre | |

| MOT #4 | 2023-04-05 14:00 |
|---|------------------|
| MOT test number | 792808687436 |
| Result | ✓ Passed |
| Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) | |

| MOT #3 | | 2022-04-05 10:10 |
|---|--|------------------|
| MOT test | number | 230726569932 |
| Result | | ✓ Passed |
| Advice | Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii |)) |
| Advice Rear Tyre worn close to legal limit/worn on edge ns os (5.2.3 (e)) | | |

CarCheck.co.uk page 3/11



Fail

OV18EFO report date: 2024-03-29

MOT #2 2021-04-07 16:40

MOT test number 700423360559

Result ✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2021-04-07 10:15

MOT test number 872349013962

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



| Tax status | Valid until 1 September |
|------------------|-------------------------|
| Days left | 126 |
| MOT expiry date | 10 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|--|------------|
| Band | Н |
| First licence fee (12 months) | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date
Category
Type

Damage 2

Date

Category

Type



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

| For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download to | |
|---|-------------|
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| | |
| *********** | |
| | More info > |
| Plate changes | |
| See in this check if this LAND ROVER had different number plates. | |
| Number of plates | |
| Current registration | NIK. |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 7 |
| First mileage registration | 2018-04-11 |
| Last registration | 2024-04-10 |
| Complete history | See info |



| Registration #1 | 2018-04-11 | 10 mi |
|-----------------|------------|-----------|
| Registration #2 | 2021-04-07 | 44.729 mi |
| Registration #3 | 2021-04-07 | 44.731 mi |
| Registration #4 | | 77,777 66 |
| Registration #5 | | 11.777 es |
| Registration #6 | | 0.00 44 |
| Registration #7 | | 11.777 no |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 93% |
| Children | 83% |
| Pedestrian | 69% |
| Safety systems | 82% |
| Overall rating | 84% |
| Video | see crash video |



Dimensions & weight

| Width | 2173 mm |
|---------------------|---------|
| Height | 1724 mm |
| Length | 4599 mm |
| Wheel base | 2741 mm |
| Kerb weight | 1845 kg |
| Max. allowed weight | 2660 kg |

Additional information

| Fuel tank capacity | 54 I |
|--------------------|-------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of axles | 2 |
| Engine number | 180226W0491204DTD |

CarCheck.co.uk page 11/11