



PJI4DVZ

report date: 2024-03-28

General information

Make	SUZUKI
Model	SX4 SZ4
Colour	White
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	156 Nm at 4.400 rpm
Engine capacity	1.586 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	58.9 mpg
Consumption combined	51.4 mpg
CO2 emission	127 g/km
CO2 label	D






Internet history

Entry 1

Date	2021-06-12
Pictures	1
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-20
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	18
Total items failed	0

MOT #7 2023-05-31 12:06

MOT test number 322534557697

Result ✓ Passed

Next expiry date 2024-06-20

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6 2022-06-18 09:07

MOT test number 660156480428

Result ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2021-06-21 13:50

MOT test number 887319629276

Result ✓ Passed

**MOT #4** 2020-05-07 11:25**MOT test number** 794631757861**Result** ✓ Passed

- Advice** Outer sill covers fitted restricting inspection of some components
- Advice** Covers fitted under vehicle restricting inspection of some components
- Advice** Unable to fully view condition of brakes without removing roadwheels, advise further inspection

MOT #3 2019-05-08 11:55**MOT test number** 498444216402**Result** ✓ Passed

- Minor** Tyre pressure monitoring system warning lamp indicates a fault (5.2.3 (h) (i))
- Advice** Outer sill covers fitted restricting inspection of some components
- Advice** Covers fitted under vehicle restricting inspection of some components

MOT #2 2018-05-11 09:43**MOT test number** 603314659621**Result** ✓ Passed

- Advice** Outer sill covers fitted restricting inspection of some components
- Advice** Covers fitted under vehicle restricting inspection of some components

MOT #1 2017-05-15 10:03**MOT test number** 152668239053**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit on 2mm -- 205 50 17 -- (4.1.E.1)
- Advice** Offside Front Tyre worn close to the legal limit on 2mm Damage To Outer Sidewall Not Deep Enough To Reach cords (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit on 3mm (4.1.E.1)
- Advice** Nearside Front Damage To Bumper And Wing



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
20 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2014-05-15
Last registration	2023-05-31
Complete history	See info



Registration #1	2014-05-15	13 mi
Registration #2	2017-05-15	25.477 mi
Registration #3	2018-05-11	29.031 mi
Registration #4	2019-05-08	31.022 mi
Registration #5	2020-05-07	33.250 mi
Registration #6	2021-05-07	35.277 mi
Registration #7	2022-05-07	36.277 mi
Registration #8	2023-05-07	37.277 mi
Registration #9	2023-05-31	38.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	80%
Pedestrian	72%
Safety systems	81%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1765 mm
Height	1580 mm
Length	4300 mm
Wheel base	2600 mm
Kerb weight	1160 kg
Max. allowed weight	1730 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	M16A-1788828