





report date: 2024-03-29

General information

Make	CITROEN
Model	C3 PICASSO BLUEHDI FEEL S/S EAT6
Colour	White
Year of manufacture	2017
Top speed	117 mph
0 - 60 mph	11.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	118 BHP
Max. torque	300 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	65.7 mpg
Consumption extra urban	80.7 mpg
Consumption combined	74.3 mpg
CO2 emission	100 g/km
CO2 label	A



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-05-22

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



MD66YTO report date: 2024-03-29

MOT history

MOT expiry date	2025-03-15
MOT pass rate	100 %
MOT passed	5
Failed MOT tests	0
Total advice items	12
Total items failed	0

MOT #5		2024-03-05 09:49
MOT test	number	129883489848
Result		✓ Passed
Next expi	ry date	2025-03-15
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2023-03-15 14:56
MOT test number	100193815523
Result	✓ Passed
MOT #3	2022-03-16 08:45
MOT test number	795804063161
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT #2 2021-02-10 12:19

MOT test number 642018940527

Result ✓ Passed

Advice Vehicle is fitted with under tray/shield so there is a restricted view of some testable items.

Advice Nearside Front Tyre slightly damaged Slight damage to outer side wall. (5.2.3 (d) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice TPS Light on during test indicating there is low pressure in one or more tyres.

Advice Nearside Front Tyre worn close to legal limit/worn on edge Worn on inner and outer edge also cracking between treads. *Advise Replacement* Size 205/45 R17 (5.2.3 (e))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Nail in tyre

Advice Offside Front Tyre worn close to legal limit/worn on edge Heavily worn on inner edge also cracking between treads. *Advise Replacement* Size 205/45 R17 (5.2.3 (e))

MOT #1 2020-01-04 09:06

MOT test number 321417206712

Result

Passed

Advice Tyre slightly damaged/cracking or perishing All four tyres starting to crack between treads. (5.2.3 (d) (ii))

Advice Vehicle is fitted with under tray/shields so there is a restricted view of some testable items.

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	33
MOT expiry date	15 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

\sim	
Owner	nictory
CVVIICI	HISLULV
~	,

For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r	
manners of the contract of the	

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Flate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-02-22
Last registration	2024-03-05
Complete history	See info



Registration #1	2017-02-22	10 mi
Registration #2	2020-01-04	13.338 mi
Registration #3	2021-02-10	20.813 mi
Registration #4	2022-03-16	28.846 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Safety ratings

NCAP rating	****	

Video <u>see crash video</u>

Dimensions & weight

Width	1826 mm
Height	1625 mm
Length	4428 mm
Wheel base	2785 mm
Kerb weight	1320 kg
Max. allowed weight	1975 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	JBHD3066007

CarCheck.co.uk page 11/11