



TOYOTA

N9I6MGT

report date: 2024-03-29

General information

Make	TOYOTA
Model	CELICA
Colour	Black
Year of manufacture	1996
Gearbox	-

Engine & fuel consumption

Engine capacity	1.998 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-08-11
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-08-04
Pictures	5
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2023-06-23
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	50
Total items failed	9

MOT #21	2023-08-16 14:24
---------	------------------

MOT test number	341319382011
-----------------	--------------

Result	✗ Failed
MAJOR	Nearside Front Direction indicator not working (4.4.1 (a) (ii))
MAJOR	Front Windscreen washer not working (3.5 (a))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Rear brake back plate corroded and holed
MAJOR	Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
Advice	Rear rear seats removed at time of test seat belts not tested
MAJOR	Offside Front Direction indicator not working (4.4.1 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))
Advice	Offside Rear brake back plate corroded and holed
MAJOR	Exhaust carbon monoxide content at idle exceeds default limits (8.2.1.2 (b))
Advice	Nearside Front seat belt trim insecure jamming belt returning

**MOT #20**

2022-06-24 11:18

**MOT test number**

302247026549

**Result**

✓ Passed

**Advice**

Nearside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #19**

2022-05-10 09:52

**MOT test number**

710862411392

**Result**

✗ Failed

**MAJOR**

Front passenger door cannot be opened from outside the vehicle window tapped up (6.2.3 (a))

**Advice**

Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Minor**

Nearside Front Drive shaft joint constant velocity boot severely deteriorated leaking (6.1.7 (g) (i))

**MAJOR**

Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

**MAJOR**

Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))

**MAJOR**

Exhaust has a major leak of exhaust gases (6.1.2 (a))

**MOT #18**

2020-09-30 15:25

**MOT test number**

957187430169

**Result**

✓ Passed

**Advice**

Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**Advice**

Nearside Rear brake back plate corroded

**MOT #17**

2019-09-30 07:38

**MOT test number**

744491896606

**Result**

✓ Passed

**MOT #16**

2019-09-16 07:42

**MOT test number**

972275469827

**Result****✗ Failed**

- MAJOR** Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits (8.2.1.2 (a))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Offside Front Service brake lagging in operation (1.2.1 (d))
- MAJOR** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- MAJOR** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #15**

2018-09-24 12:59

**MOT test number**

140678309318

**Result****✓ Passed**

- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))

**MOT #14**

2018-09-15 08:02

**MOT test number**

508093356494

**Result****✗ Failed**

- Advice** Nearside Rear Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))
- MAJOR** Nearside Rear Service brake lagging in operation (1.2.1 (d))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))

**MOT #13** 2017-09-16 08:28**MOT test number** 552429041659**Result** ✓ Passed**MOT #12** 2015-06-16 16:40**MOT test number** 758557565104**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #11** 2015-06-16 13:06**MOT test number** 509887265192**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Nearside Side repeater not working (1.4.A.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Registration plate lamp not working (1.1.C.1d)**MOT #10** 2014-06-12 14:49**MOT test number** 309643964125**Result** ✓ Passed**MOT #9** 2012-05-23 16:09**MOT test number** 475604542180**Result** ✓ Passed



MOT #8	2012-05-23 15:26
MOT test number	448234242197
Result	✗ Failed
Fail	Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)
Notice	Oil leak
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

MOT #7	2011-05-11 14:02
MOT test number	375051531163
Result	✓ Passed
Notice	Unable too see inner rear brake linings
Notice	Front brake discs worn
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Nearside front tyre cracking

**MOT #6** 2011-05-10 17:11**MOT test number** 938910531182**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Front brake discs worn**Advice** Nearside Front constant velocity joint gaiter deteriorated (2.5.C.1a)**Notice** Nearside front tyre cracking**Fail** Offside Front constant velocity joint gaiter split (2.5.C.1a)**Notice** Unable too see inner rear brake linings**MOT #5** 2010-05-28 09:45**MOT test number** 441998740149**Result** ✓ Passed**MOT #4** 2009-04-09 15:03**MOT test number** 711519599030**Result** ✓ Passed**MOT #3** 2007-09-21 16:33**MOT test number** 851174567224**Result** ✓ Passed**MOT #2** 2006-09-28 16:56**MOT test number** 872321976243**Result** ✓ Passed





MOT #1	2005-08-27 11:49
MOT test number	122109435278
Result	✓ Passed



Tax & MOT check

✕  
Untaxed

Tax expired:  
1 October 2023

✕  
MOT

Expired:  
23 June 2023

Tax status	Expired at 1 October 2023
Days left	210 days too late
MOT expiry date	23 June 2023
Full MOT history	<a href="#">See MOT history</a>



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	1996-05-30
Last registration	2023-08-16
Complete history	<a href="#">See info</a>



Registration #1	1996-05-30	21 mi
Registration #2	2005-08-27	59.390 mi
Registration #3	2006-09-28	66.295 mi
Registration #4	2007-09-21	73.456 mi
Registration #5	2009-04-09	83.117 mi
Registration #6	2010-05-28	88.661 mi
Registration #7	2011-05-10	92.627 mi
Registration #8	2011-05-11	92.627 mi
Registration #9	2012-05-23	99.182 mi
Registration #10	2012-05-23	99.183 mi
Registration #11	2014-06-12	102.157 mi
Registration #12	2015-06-16	103.661 mi
Registration #13	2016-06-16	103.661 mi
Registration #14	2016-06-16	103.661 mi
Registration #15	2016-06-16	103.661 mi
Registration #16	2016-06-16	103.661 mi
Registration #17	2016-06-16	103.661 mi
Registration #18	2016-06-16	103.661 mi
Registration #19	2016-06-16	103.661 mi
Registration #20	2016-06-16	103.661 mi
Registration #21	2016-06-16	103.661 mi
Registration #22	2016-06-16	103.661 mi
Registration #23	2016-06-16	103.661 mi
Registration #24	2016-06-16	103.661 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats	2
Engine number	NOTKNOWN