



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	RAV-4 VVT-I XT4
Colour	Grey
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	147 BHP
Max. torque	192 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	24.8 mpg
Consumption extra urban	38.7 mpg
Consumption combined	32.1 mpg
CO2 emission	211 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-12-16
Pictures	18
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-10-25
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	34
Total items failed	7

MOT #20	2021-10-26 14:09
MOT test number	163785084079
Result	✓ Passed
Next expiry date	2022-10-25

MOT #19	2020-08-11 15:13
MOT test number	878463921888
Result	✓ Passed
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18	2020-08-10 13:59
MOT test number	346879494082
Result	✗ Failed
Minor	Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Minor	Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))
MAJOR	Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #17** 2019-07-11 16:20**MOT test number** 735415937484**Result** ✓ Passed**MOT #16** 2019-07-11 09:06**MOT test number** 983027143818**Result** ✗ Failed**MAJOR** Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Offside Front Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Minor** Nearside Front Headlamp lens slightly defective (4.1.1 (b) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #15** 2018-08-08 10:39**MOT test number** 708630317168**Result** ✓ Passed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #14** 2018-08-07 15:13**MOT test number** 422968784857**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #13**

2018-08-03 16:02

MOT test number

365953654657

Result

✗ Failed

Advice Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Offside Headlamp lens slightly defective deteriorated and beam image poor (4.1.1 (b) (i))**MAJOR** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Nearside Headlamp lens slightly defective deteriorated and beam image poor (4.1.1 (b) (i))**MOT #12**

2017-07-20 11:24

MOT test number

784497707300

Result

✓ Passed

Advice O/s mirror damaged**MOT #11**

2016-08-05 13:31

MOT test number

468410491571

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear exhaust flange centre/rear in poor condition

**MOT #10** 2016-08-05 08:44**MOT test number** 795094312455**Result** ✗ Failed

- Fail** Offside Headlamp aim too low (1.8)
- Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Rear exhaust flange centre/rear in poor condition
- Fail** Nearside Headlamp aim too low (1.8)
- Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #9 2015-08-06 10:12**MOT test number** 347478915273**Result** ✓ Passed

- Notice** Headlamp masks/converters fitted

MOT #8 2014-07-22 16:59**MOT test number** 375523904299**Result** ✓ Passed

- Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)

MOT #7 2013-08-02 14:48**MOT test number** 329734813262**Result** ✓ Passed**MOT #6** 2012-08-03 15:12**MOT test number** 245386612229**Result** ✓ Passed

**MOT #5** 2011-08-06 10:14**MOT test number** 807968411282**Result** ✓ Passed**Notice** Rear tyres cracking and getting low on inner edges. O/S/R 2.5mm. N/S/R 3mm.**MOT #4** 2011-08-06 08:47**MOT test number** 795918411227**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Rear tyres cracking and getting low on inner edges. O/S/R 2.5mm. N/S/R 3mm.**MOT #3** 2011-01-20 11:59**MOT test number** 378370021012**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-01-26 11:46**MOT test number** 652676020004**Result** ✓ Passed**MOT #1** 2009-01-26 15:17**MOT test number** 691196729088**Result** ✓ Passed



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2005-11-29
Last registration	2021-10-26
Complete history	See info



Registration #1	2005-11-29	9 mi
Registration #2	2009-01-26	41.319 mi
Registration #3	2010-01-26	46.672 mi
Registration #4	2011-01-20	51.920 mi
Registration #5	2011-08-06	54.122 mi
Registration #6	2011-08-06	54.122 mi
Registration #7	2012-08-03	63.520 mi
Registration #8	2013-08-02	73.321 mi
Registration #9	2014-07-22	83.055 mi
Registration #10	2015-08-06	94.353 mi
Registration #11	2016-08-05	106.808 mi
Registration #12	2017-08-05	119.263 mi
Registration #13	2018-08-05	131.718 mi
Registration #14	2019-08-05	144.173 mi
Registration #15	2020-08-05	156.628 mi
Registration #16	2021-08-05	169.083 mi
Registration #17	2022-08-05	181.538 mi
Registration #18	2023-08-05	193.993 mi
Registration #19	2024-08-05	206.448 mi
Registration #20	2025-08-05	218.903 mi
Registration #21	2026-08-05	231.358 mi
Registration #22	2027-08-05	243.813 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1785 mm
Height	1710 mm
Length	4260 mm
Wheel base	2490 mm
Kerb weight	1385 kg
Max. allowed weight	1825 kg

Additional information

Fuel tank capacity	57 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1AZ1653805