



HONDA



report date: 2024-03-28

General information

Make	HONDA
Model	FR-V I-CTDI EX
Colour	Silver
Year of manufacture	2009
Top speed	118 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	2.204 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	52.3 mpg
Consumption combined	44.8 mpg
CO2 emission	167 g/km
CO2 label	H







Internet history

Entry 1

Date	2021-10-31
Pictures	13
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-26
MOT pass rate	60 %
MOT passed	12
Failed MOT tests	8
Total advice items	28
Total items failed	7

MOT #20	2024-02-15 11:20
MOT test number	817480555641
Result	✓ Passed
Next expiry date	2025-02-26
Advice	Offside Rear Coil spring corroded Just starting to corrode (5.3.1 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Coil spring corroded Just starting to corroded (5.3.1 (b) (i))

MOT #19	2024-02-15 11:19
MOT test number	505470552102
Result	✗ Failed
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Pass with rectification	Nearside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Coil spring corroded Just starting to corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded Just starting to corrode (5.3.1 (b) (i))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))



<b>MOT #18</b>	2023-02-27 17:40
----------------	------------------

<b>MOT test number</b>	231183169653
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #17</b>	2021-11-03 20:21
----------------	------------------

<b>MOT test number</b>	996581073350
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #16</b>	2021-11-01 12:06
----------------	------------------

<b>MOT test number</b>	704363470914
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

**DANGEROUS** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**MAJOR** Windscreen washer not working (3.5 (a))

<b>MOT #15</b>	2020-10-28 12:47
----------------	------------------

<b>MOT test number</b>	734665308712
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

<b>MOT #14</b>	2020-10-28 12:47
----------------	------------------

<b>MOT test number</b>	869562335227
------------------------	--------------

<b>Result</b>	✗ Failed
---------------	----------

**Pass with rectification** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

<b>MOT #13</b>	2019-10-01 16:44
----------------	------------------

<b>MOT test number</b>	639314664653
------------------------	--------------

<b>Result</b>	✓ Passed
---------------	----------

**MOT #12** 2019-10-01 13:34**MOT test number** 228186297418**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #11** 2018-10-11 10:02**MOT test number** 532912708652**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #10** 2017-10-17 10:08**MOT test number** 230473832381**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Rear Nail in tyre**MOT #9** 2016-10-06 14:36**MOT test number** 213400888181**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)

**MOT #8** 2016-10-06 14:36**MOT test number** 256649902421**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit edges (4.1.E.1)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively 26" (8.2.2)**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively 20" (8.2.2)**MOT #7** 2015-09-17 09:38**MOT test number** 625403626099**Result** ✓ Passed**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front tyre wearing inner and outer edge**MOT #6** 2015-09-17 08:33**MOT test number** 363605044135**Result** ✗ Failed**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Parking brake lever has little reserve travel (3.1.6b)**Advice** Nearside Front tyre wearing inner and outer edge**MOT #5** 2014-10-22 14:03**MOT test number** 788345794232**Result** ✓ Passed

**MOT #4** 2014-10-22 12:20**MOT test number** 338215694485**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Offside rear tyre has cracks or slightly perished on tread**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #3** 2013-09-13 12:40**MOT test number** 568786453239**Result** ✓ Passed**MOT #2** 2013-09-13 12:40**MOT test number** 386656953461**Result** ✗ Failed**Pass with rectification** Parking brake lever has no reserve travel (3.1.6b)**MOT #1** 2012-09-29 13:18**MOT test number** 259793272224**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
26 February 2025

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	63
<b>MOT expiry date</b>	26 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-





Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01
Current registration	<b>XXXXXX</b>
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-09-23
Last registration	2024-02-15
Complete history	<a href="#">See info</a>



Registration #1	2009-09-23	20 mi
Registration #2	2012-09-29	26.791 mi
Registration #3	2013-09-13	35.416 mi
Registration #4	2014-10-22	38.739 mi
Registration #5	2014-10-22	38.739 mi
Registration #6	2015-09-17	40.539 mi
Registration #7	2015-09-17	40.539 mi
Registration #8	2016-10-06	42.779 mi
Registration #9	2016-10-06	42.779 mi
Registration #10	2017-10-17	44.262 mi
Registration #11	2018-10-11	44.648 mi
Registration #12	2019-09-23	45.000 mi
Registration #13	2019-09-23	45.000 mi
Registration #14	2019-09-23	45.000 mi
Registration #15	2019-09-23	45.000 mi
Registration #16	2019-09-23	45.000 mi
Registration #17	2019-09-23	45.000 mi
Registration #18	2019-09-23	45.000 mi
Registration #19	2019-09-23	45.000 mi
Registration #20	2019-09-23	45.000 mi
Registration #21	2019-09-23	45.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1810 mm
Height	1625 mm
Length	4285 mm
Wheel base	2680 mm
Kerb weight	1573 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	N22A14500087