



report date: 2024-03-29

General information

Make	AUDI
Model	A3 AVANT TDI DPF S LINE
Colour	Blue
Year of manufacture	2009
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	320 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-04-26
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	19
Total items failed	10

MOT #17	2024-04-27 07:54
MOT test number	200041271560
Result	✓ Passed
Next expiry date	2025-04-26
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #16	2023-04-24 16:51
MOT test number	621543969155
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Nail in tyre

MOT #15	2023-04-24 16:51
MOT test number	402281392582
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Rear Nail in tyre
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #14	2022-04-04 18:00
MOT test number	456521325285
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2021-04-06 18:24
MOT test number	949833956165
Result	✓ Passed

MOT #12	2020-02-25 16:53
MOT test number	262463350650
Result	✓ Passed
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #11	2020-02-25 10:02
MOT test number	678259744590
Result	✗ Failed
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Offside Front Upper Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Fail	Nearside Front Lower Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))



MOT #10	2019-03-04 14:46
MOT test number	394377390427
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #9	2019-03-04 11:59
MOT test number	707993214693
Result	✗ Failed
Fail	Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #8	2018-03-06 17:35
MOT test number	670242148840
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #7	2017-03-29 15:41
MOT test number	396227381315
Result	✓ Passed

MOT #6	2016-03-24 13:45
MOT test number	247054369570
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2015-04-18 11:59**MOT test number** 797108605157**Result** ✓ Passed**MOT #4** 2014-05-21 12:24**MOT test number** 498121144178**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2013-05-16 16:40**MOT test number** 288196133173**Result** ✓ Passed**MOT #2** 2013-05-16 10:29**MOT test number** 977156833191**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**MOT #1** 2012-05-24 11:37**MOT test number** 546305142165**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 April 2025

Tax status	Valid until 1 October
Days left	154
MOT expiry date	26 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-04
Last registration	2024-04-27
Complete history	See info



Registration #1	2009-06-04	26 mi
Registration #2	2012-05-24	19.095 mi
Registration #3	2013-05-16	23.397 mi
Registration #4	2013-05-16	23.397 mi
Registration #5	2014-05-21	28.920 mi
Registration #6	2015-04-18	34.965 mi
Registration #7	2016-03-24	55.131 mi
Registration #8	2017-03-29	65.454 mi
Registration #9	2018-03-06	87.812 mi
Registration #10	2019-03-20	101.377 mi
Registration #11	2019-03-20	101.377 mi
Registration #12	2019-03-20	101.377 mi
Registration #13	2019-03-20	101.377 mi
Registration #14	2019-03-20	101.377 mi
Registration #15	2019-03-20	101.377 mi
Registration #16	2019-03-20	101.377 mi
Registration #17	2019-03-20	101.377 mi
Registration #18	2019-03-20	101.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1826 mm
Height	1436 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1520 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	CAG 268091