



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	VERSO D-4D TR
Colour	Silver
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	310 Nm at 1.800 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	61.4 mpg
Consumption combined	53.3 mpg
CO2 emission	143 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-08-31
Pictures	9
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2022-02-17
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	42
Total items failed	9

MOT #14 2021-02-18 14:28

MOT test number 325267621046

Result ✓ Passed

Next expiry date 2022-02-17

- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13 2021-02-17 16:08

MOT test number 454595516167

Result ✗ Failed

- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Parking brake inoperative on one side (1.4.1 (a))
- Fail** Offside Rear Seat belt damaged last row (7.1.2 (b) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement

**MOT #12**

2020-08-20 08:26

**MOT test number**

602974567718

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2020-08-19 16:01

**MOT test number**

584841384937

**Result**

✗ Failed

**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))

**Fail** Offside Headlamp aim too low (4.1.2 (a))

**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #10**

2019-08-22 14:00

**MOT test number**

216651223422

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))

**MOT #9**

2019-08-22 11:18

**MOT test number**

785096114818

**Result**

✗ Failed

- Fail** Offside Rear Body panel damaged and likely to cause injury bumper (6.2.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Front Brake pad(s) wearing thin nearside and offside (1.1.13 (a) (ii))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material to flexi (1.1.11 (c))
- Advice** Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D Bush (5.3.4 (a) (i))



MOT #8 2018-09-21 14:48

MOT test number 204722227682

Result ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))

MOT #7 2018-09-21 10:44

MOT test number 709956221269

Result ✗ Failed

- Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Nearside Front Upper Shock absorbers has a slightly worn bush (5.3.2 (c))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #6** 2017-09-22 10:42**MOT test number** 715774126774**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-09-16 10:39**MOT test number** 559160779528**Result** ✓ Passed**MOT #4** 2015-10-09 11:06**MOT test number** 186504383859**Result** ✓ Passed**MOT #3** 2014-10-10 13:13**MOT test number** 185883084243**Result** ✓ Passed**MOT #2** 2013-09-17 16:12**MOT test number** 258300963235**Result** ✓ Passed**MOT #1** 2012-09-29 11:15**MOT test number** 408323172226**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
31 October 2021

X

MOT

Expired:  
17 February 2022

Tax status	Expired at 31 October 2021
Days left	911 days too late
MOT expiry date	17 February 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-10-13
Last registration	2021-02-18
Complete history	<a href="#">See info</a>



Registration #1	2009-10-13	22 mi
Registration #2	2012-09-29	45.461 mi
Registration #3	2013-09-17	59.957 mi
Registration #4	2014-10-10	77.367 mi
Registration #5	2015-10-09	95.368 mi
Registration #6	2016-09-16	111.650 mi
Registration #7	2017-09-22	128.100 mi
Registration #8	2018-09-21	147.147 mi
Registration #9	2019-09-20	166.194 mi
Registration #10	2020-09-19	185.241 mi
Registration #11	2021-09-18	204.288 mi
Registration #12	2022-09-17	223.335 mi
Registration #13	2023-09-16	242.382 mi
Registration #14	2024-09-15	261.429 mi
Registration #15	2025-09-14	280.476 mi
Registration #16	2026-09-13	299.523 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1625 kg
Max. allowed weight	2260 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

Engine number	1AF5454242
---------------	------------