



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC
Colour	Black
Year of manufacture	2009
Top speed	115 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	143 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.7 mpg
Consumption extra urban	51.4 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-19
Pictures	17
Listing price	<a href="#">View report</a>



source: autotrader.co.uk



MOT history

MOT expiry date	2024-09-17
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	38
Total items failed	12

MOT #17	2023-09-18 15:47
MOT test number	873439206039
Result	✓ Passed
Next expiry date	2024-09-17
Advice	Oil leak, but not excessive gear box (8.4.1 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Rear back box mounting corroded
Advice	Rear Coil spring corroded rears (5.3.1 (b) (i))

**MOT #16**

2022-09-08 15:38

**MOT test number**

764184249209

**Result**

✓ Passed

- Advice** Rear Rear arms corroded
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both fronts (4.1.4 (b))
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Exhaust mounting defective Rear box broken (6.1.2 (a))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive G box (8.4.1 (a) (i))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #15**

2022-09-03 11:48

**MOT test number**

165484255745

**Result**

✗ Failed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Oil leak, but not excessive G box (8.4.1 (a) (i))
- Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Rear Rear arms corroded
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Rear Exhaust mounting defective Rear box broken (6.1.2 (a))
- Advice** Front Headlamp has a product on the lens but not seriously reducing light output Both fronts (4.1.4 (b))
- Fail** Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #14**

2021-09-08 14:31

**MOT test number**

338830603112

**Result**

✓ Passed

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Bushes cracking & perishing (5.3.4 (a) (i))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Advice** Rear Exhaust mounting defective Corroded (6.1.2 (a))

**MOT #13**

2021-09-08 09:51

**MOT test number**

961392241948

**Result**

✗ Failed

**Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Bushes cracking & perishing (5.3.4 (a) (i))

**Fail** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Fail** Nearside Front Tyre has a tear, caused by separation or partial failure of its structure 205/50/17 (5.2.3 (d) (ii))

**Advice** Rear Exhaust mounting defective Corroded (6.1.2 (a))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge 205/50/17 - 2mm tread depth remaining heavily worn on edges (5.2.3 (e))

**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #12**

2020-09-04 08:01

**MOT test number**

820049436738

**Result**

✓ Passed

**MOT #11**

2019-09-17 09:12

**MOT test number**

753329483390

**Result**

✓ Passed

- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Oil level low
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #10**

2019-09-16 14:59

**MOT test number**

453031181109

**Result**

✗ Failed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Offside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Rear Anti-roll bar linkage fractured (5.3.3 (b) (ii))
- Advice** Oil level low
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**MOT #9**

2018-08-23 10:59

**MOT test number**

876084028326

**Result**

✓ Passed

**MOT #8**

2017-09-04 15:56

**MOT test number**

718266361921

**Result**

✓ Passed

**MOT #7** 2017-09-04 11:50**MOT test number** 572802319760**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm 205/50r17 (4.1.E.1)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #6** 2016-08-31 10:06**MOT test number** 139827049643**Result** ✓ Passed**MOT #5** 2015-09-07 11:58**MOT test number** 752122742422**Result** ✓ Passed**MOT #4** 2015-09-07 11:58**MOT test number** 946135545309**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #3** 2014-08-29 14:33**MOT test number** 659941944292**Result** ✓ Passed**MOT #2** 2013-09-07 12:00**MOT test number** 386270653268**Result** ✓ Passed**Advice** Tyre worn close to the legal limit (4.1.E.1)**Notice** Both rear tyres are getting low on tread



MOT #1	2012-09-01 09:24
MOT test number	189875642202
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
17 September 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	17 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EX59HKM
Plate since	2019-03-29
Current registration	EX59HKM
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-09
Last registration	2023-09-18
Complete history	<a href="#">See info</a>



Registration #1	2009-09-09	16 mi
Registration #2	2012-09-01	24.477 mi
Registration #3	2013-09-07	33.921 mi
Registration #4	2014-08-29	42.736 mi
Registration #5	2015-09-07	55.224 mi
Registration #6	2015-09-07	55.224 mi
Registration #7	2016-08-31	65.352 mi
Registration #8	2017-09-04	76.137 mi
Registration #9	2017-09-04	76.138 mi
Registration #10	2018-08-23	85.198 mi
Registration #11	2019-09-01	95.257 mi
Registration #12	2019-09-01	95.257 mi
Registration #13	2019-09-01	95.257 mi
Registration #14	2019-09-01	95.257 mi
Registration #15	2019-09-01	95.257 mi
Registration #16	2019-09-01	95.257 mi
Registration #17	2019-09-01	95.257 mi
Registration #18	2019-09-01	95.257 mi
Registration #19	2019-09-01	95.257 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1998 mm
Height	1430 mm
Length	4152 mm
Wheel base	2640 mm
Kerb weight	1277 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9U51607