



report date: 2024-03-28

General information

| | |
|---------------------|----------------------|
| Make | FORD |
| Model | FUSION ZETEC CLIMATE |
| Colour | Blue |
| Year of manufacture | 2007 |
| Top speed | 102 mph |
| 0 - 60 mph | 14.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 79 BHP |
| Max. torque | 124 Nm at 3.500 rpm |
| Engine capacity | 1.388 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 35.3 mpg |
| Consumption extra urban | 54.3 mpg |
| Consumption combined | 45.6 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2022-08-10 |
| Pictures | 9 |
| Listing price | View report |



source: cargurus.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-09-05 |
| MOT pass rate | 88 % |
| MOT passed | 14 |
| Failed MOT tests | 2 |
| Total advice items | 19 |
| Total items failed | 3 |

| | |
|------------------|------------------|
| MOT #16 | 2023-09-04 09:43 |
| MOT test number | 759226784398 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-05 |

| | |
|-----------------|------------------|
| MOT #15 | 2022-09-06 14:09 |
| MOT test number | 975858385141 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #14 | 2021-12-02 14:29 |
| MOT test number | 430386490188 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Advice | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #13 | 2020-12-01 14:09 |
| MOT test number | 378317795802 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #12 | 2019-11-22 09:40 |
| MOT test number | 593194366882 |
| Result | ✓ Passed |



| | |
|----------------|------------------|
| MOT #11 | 2018-11-28 10:14 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 516626334501 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|----------------|------------------|
| MOT #10 | 2017-11-14 16:29 |
|----------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 741157816000 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #9 | 2017-11-14 12:06 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 470867293642 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✗ Failed |
|---------------|----------|

Advice Front pas pipe broken clip

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Advice Rear heat shield loose

| | |
|---------------|------------------|
| MOT #8 | 2016-11-16 14:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 623939307910 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

| | |
|---------------|------------------|
| MOT #7 | 2015-11-13 10:07 |
|---------------|------------------|

| | |
|------------------------|--------------|
| MOT test number | 746002448687 |
|------------------------|--------------|

| | |
|---------------|----------|
| Result | ✓ Passed |
|---------------|----------|

**MOT #6** 2014-11-14 09:49**MOT test number** 107588514362**Result** ✓ Passed

- Notice** All brake pipes starting to corrode
- Notice** N/s/f cv gaiter leaking grease
- Notice** N/s/r tyre starting to perish
- Notice** Power steering pipes corroding on rack

MOT #5 2013-12-04 15:51**MOT test number** 336418233315**Result** ✓ Passed

- Notice** Fuel lines under car starting to corrode
- Notice** Power steering pipe under steering rack corroding
- Notice** Light corrosion to all brake pipes
- Notice** Front brake disc's corroding

MOT #4 2013-12-04 11:50**MOT test number** 468638433469**Result** ✗ Failed

- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Light corrosion to all brake pipes
- Advice** Nearside Front Brake hose has slight corrosion to ferrules (3.6.B.4e)
- Notice** Front brake disc's corroding
- Notice** Fuel lines under car starting to corrode
- Fail** Offside Front Brake hose ferrule excessively corroded (3.6.B.4e)
- Notice** Power steering pipe under steering rack corroding



| | |
|-------------------|---|
| MOT #3 | 2012-11-29 12:35 |
| MOT test number | 759694132321 |
| Result | ✓ Passed |
| <div>Advice</div> | Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a) |
| <div>Notice</div> | Off side rear tyre starting to crack |

| | |
|-----------------|------------------|
| MOT #2 | 2011-12-01 13:17 |
| MOT test number | 368275131318 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #1 | 2010-12-06 15:58 |
| MOT test number | 440150740388 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
5 September 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 September |
| Days left | 125 |
| MOT expiry date | 5 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | ***** |
| Plate since | 2019-06-29 |
| Current registration | ***** |
| Plate since | 2019-06-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|----------|------|
| Finance company | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type | XXXXXXXX | XXXX |
| Agreement term | XXXXXXXX | XXXX |
| Agreement number | XXXXXXXX | XXXX |
| Contact info | XXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 18 |
| First mileage registration | 2007-12-07 |
| Last registration | 2023-09-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2007-12-07 | 11 mi |
| Registration #2 | 2010-12-06 | 13.998 mi |
| Registration #3 | 2011-12-01 | 18.841 mi |
| Registration #4 | 2012-11-29 | 22.822 mi |
| Registration #5 | 2013-12-04 | 24.571 mi |
| Registration #6 | 2013-12-04 | 24.571 mi |
| Registration #7 | 2014-11-14 | 26.902 mi |
| Registration #8 | 2015-11-13 | 28.759 mi |
| Registration #9 | 2016-11-16 | 30.682 mi |
| Registration #10 | 2016-11-16 | 30.682 mi |
| Registration #11 | 2016-11-16 | 30.682 mi |
| Registration #12 | 2016-11-16 | 30.682 mi |
| Registration #13 | 2016-11-16 | 30.682 mi |
| Registration #14 | 2016-11-16 | 30.682 mi |
| Registration #15 | 2016-11-16 | 30.682 mi |
| Registration #16 | 2016-11-16 | 30.682 mi |
| Registration #17 | 2016-11-16 | 30.682 mi |
| Registration #18 | 2016-11-16 | 30.682 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1963 mm |
| Height | 1543 mm |
| Length | 4013 mm |
| Wheel base | 2485 mm |
| Kerb weight | 1199 kg |
| Max. allowed weight | 1605 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |

| | |
|-----------------|---------|
| Number of axles | 2 |
| Engine number | 7C04367 |