




General information

Make	MINI
Model	COOPER S CLUBMAN
Colour	Blue
Year of manufacture	2013
Top speed	141 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	38.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





**Internet history**

---

**Entry 2**

Date	2023-12-13
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](http://carcraft.co.uk)

**Entry 1**

Date	2023-04-26
Pictures	0
Listing price	<a href="#">View report</a>

source: [carcraft.co.uk](http://carcraft.co.uk)



MOT history

MOT expiry date	2025-02-26
MOT pass rate	100 %
MOT passed	9
Failed MOT tests	0
Total advice items	6
Total items failed	0

<b>MOT #9</b>	2024-02-27 11:59
MOT test number	360891689141
Result	✓ Passed
Next expiry date	2025-02-26

<b>MOT #8</b>	2023-01-16 14:53
MOT test number	555844156193
Result	✓ Passed
<b>Advice</b>	Offside Rear Child Seat fitted not allowing full inspection of adult belt
<b>Advice</b>	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #7</b>	2022-01-11 16:42
MOT test number	627343689796
Result	✓ Passed
<b>Advice</b>	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

<b>MOT #6</b>	2021-01-14 15:52
MOT test number	566787249383
Result	✓ Passed



<b>MOT #5</b>	2019-07-17 15:51
<b>MOT test number</b>	825339672555
<b>Result</b>	✓ Passed
<b>Advice</b>	Various/numerous stone chip-frt windscreen-(repaired).

<b>MOT #4</b>	2019-02-25 17:07
<b>MOT test number</b>	915891660999
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front Items removed from driver's view prior to test phone holder
<b>Advice</b>	Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 25%. O/S LOWER EFFORT (1.2.1 (b) (i))

<b>MOT #3</b>	2018-02-23 09:35
<b>MOT test number</b>	489964983770
<b>Result</b>	✓ Passed

<b>MOT #2</b>	2017-10-20 07:58
<b>MOT test number</b>	943814697467
<b>Result</b>	✓ Passed

<b>MOT #1</b>	2016-10-07 14:36
<b>MOT test number</b>	623887764540
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**

**Tax due:**  
1 March 2025

✓  
**MOT**

**Expires:**  
26 February 2025

**Tax status** Valid until 1 March

**Days left** 15

**MOT expiry date** 26 February 2025

**Full MOT history** [See MOT history](#)

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-




**Damage history**

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


**Damage 1**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Damage 2**

<b>Date</b>	EXAMPLE
<b>Category</b>	EXAMPLE
<b>Type</b>	EXAMPLE



**Extra MINI salvage check**



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

**More info** >



**Vehicle valuation**

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

<b>Trade retail value</b>	£ 19,999
<b>Auction value</b>	£ 19,999
<b>Average private trade value</b>	£ 19,999

**More info** >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	<b>ML63BBJ</b>
Plate since	2019-09-25
Current registration	<b>ML63BBJ</b>
Plate since	2019-09-25

More info >





**Finance check**

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


<b>Finance company</b>	REDACTED
<b>Date of agreement</b>	REDACTED
<b>Agreement type</b>	REDACTED
<b>Agreement term</b>	REDACTED
<b>Agreement number</b>	REDACTED
<b>Contact info</b>	REDACTED

**More info** >



Mileage check

<b>Odometer</b>	In miles
<b>Mileage registrations</b>	12
<b>First mileage registration</b>	2013-11-01
<b>Last registration</b>	2024-02-27
<b>Complete history</b>	<a href="#">See info</a>



<b>Registration #1</b>	2013-11-01	16 mi
<b>Registration #2</b>	2016-10-07	14.422 mi
<b>Registration #3</b>	2017-10-20	18.322 mi
<b>Registration #4</b>	2018-02-23	18.952 mi
<b>Registration #5</b>	2019-02-25	33.950 mi
<b>Registration #6</b>	2019-07-17	37.666 mi
<b>Registration #7</b>	2019-09-27	38.277 mi
<b>Registration #8</b>	2019-11-29	38.888 mi
<b>Registration #9</b>	2020-01-30	39.499 mi
<b>Registration #10</b>	2020-03-31	40.110 mi
<b>Registration #11</b>	2020-05-31	40.721 mi
<b>Registration #12</b>	2020-07-31	41.332 mi

[More info >](#)



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1432 mm
Length	3958 mm
Wheel base	2547 mm
Kerb weight	1205 kg
Max. allowed weight	1690 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	B356J557