



report date: 2024-03-28

General information

Make	KIA
Model	SORENTO CRDI KX-3 ISG
Colour	Black
Year of manufacture	2016
Top speed	127 mph
0 - 60 mph	8.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	441 Nm at 1.750 rpm
Engine capacity	2.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	39.8 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G






Internet history

Entry 2



Date	2021-11-07
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-11-06
Pictures	12
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-07
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	1

MOT #6	2023-08-07 09:10
MOT test number	591672430465
Result	✓ Passed
Next expiry date	2024-08-07
Advice	Emissions tested no reading

MOT #5	2022-08-08 15:03
MOT test number	703756328522
Result	✓ Passed
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

MOT #4	2022-08-05 08:29
MOT test number	276944304818
Result	✗ Failed
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Side repeater with a multiple light source more than 1/2 not functioning (4.4.1 (a) (ii))
Advice	Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))



MOT #3	2021-08-06 11:38
MOT test number	862955180282
Result	✓ Passed

MOT #2	2020-02-26 16:15
MOT test number	743027326619
Result	✓ Passed
Advice	Under trays fitted obscuring some items
Advice	Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
Advice	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1	2019-03-06 11:51
MOT test number	486667940648
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 August 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	7 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this KIA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this KIA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2016-03-08
Last registration	2023-08-07
Complete history	See info



Registration #1	2016-03-08	11 mi
Registration #2	2019-03-06	13.224 mi
Registration #3	2020-02-26	16.566 mi
Registration #4	2021-08-06	19.950 mi
Registration #5	2022-08-06	25.277 mi
Registration #6	2023-08-07	25.277 mi
Registration #7	2023-08-07	25.277 mi
Registration #8	2023-08-07	25.277 mi
Registration #9	2023-08-07	25.277 mi

More info >



Car features

The KIA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete KIA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	83%
Pedestrian	67%
Safety systems	71%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1890 mm
Height	1690 mm
Length	4800 mm
Wheel base	2780 mm
Kerb weight	1932 kg
Max. allowed weight	2590 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	D4HBGH263767