



RENAULT

BAI90CV

report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | RENAULT |
| Model | ZOE DYNAMIQUE NAV |
| Colour | Blue |
| Year of manufacture | 2019 |
| Top speed | 84 mph |
| 0 - 60 mph | 11.9 seconds |
| Gearbox | 1 speed automatic |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 108 BHP |
| Max. torque | 225 Nm at 2.500 rpm |
| Fuel type | Electricity |
| Consumption combined | 1.0 mpg |



LABEL UNKNOWN



Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-04 |
| Pictures | 1 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-25 |
| MOT pass rate | 67 % |
| MOT passed | 2 |
| Failed MOT tests | 1 |
| Total advice items | 6 |
| Total items failed | 2 |

| | |
|------------------|---|
| MOT #3 | 2023-07-13 14:38 |
| MOT test number | 994971339332 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-25 |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |

| | |
|-------------------------|---|
| MOT #2 | 2023-07-13 14:38 |
| MOT test number | 322674159700 |
| Result | ✗ Failed |
| Advice | Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) |
| Pass with rectification | Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii)) |
| Pass with rectification | Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)) |

| | |
|-----------------|--|
| MOT #1 | 2022-07-19 10:51 |
| MOT test number | 129612076149 |
| Result | ✓ Passed |
| Advice | OSR, OSF and NSR tyres have small cracks appearing. |
| Advice | Offside Rear Direction indicator slightly discoloured (4.4.3 (a)) |
| Advice | Offside Front edge of tyre slightly worn |
| Advice | Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) |



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
25 July 2024

| | |
|-------------------|---------------------|
| Tax status | Valid until 1 April |
|-------------------|---------------------|

| | |
|------------------|-----|
| Days left | 337 |
|------------------|-----|

| | |
|------------------------|--------------|
| MOT expiry date | 25 July 2024 |
|------------------------|--------------|

| | |
|-------------------------|---------------------------------|
| Full MOT history | See MOT history |
|-------------------------|---------------------------------|



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this RENAULT had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | BA19OCV |
| Plate since | 2019-03-29 |
| Current registration | BA19OCV |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

| | |
|-------------------|-----------------|
| Finance company | RENAULT FINANCE |
| Date of agreement | 01/01/2024 |
| Agreement type | FINANCE |
| Agreement term | 36 months |
| Agreement number | 123456789 |
| Contact info | 0123 456789 |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2019-07-26 |
| Last registration | 2023-07-13 |
| Complete history | See info |



| | | |
|-----------------|------------|----------|
| Registration #1 | 2019-07-26 | 23 mi |
| Registration #2 | | |
| Registration #3 | 2022-07-19 | 9.349 mi |
| Registration #4 | | |
| Registration #5 | | |

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 89% |
| Children | 80% |
| Pedestrian | 66% |
| Safety systems | 85% |
| Overall rating | 82% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1945 mm |
| Height | 1562 mm |
| Length | 4084 mm |
| Wheel base | 2588 mm |
| Max. allowed weight | 1954 kg |

Additional information

| | |
|-----------------|----------------|
| Fuel delivery | Not Applicable |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | C013869 |