



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	COROLLA VERSO VVT-I SR
Colour	Black
Year of manufacture	2007
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





Internet history

Entry 2



Date	2023-08-18
Pictures	42
Listing price	View report



source: [cargurus.co.uk](#)

Entry 1

Date	2021-09-04
Pictures	18
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-26
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	63
Total items failed	15

MOT #19 2023-08-12 08:36

MOT test number 430103204177

Result ✓ Passed

Next expiry date 2024-08-26

Advice Inner Integral body structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice Front and rear suspensions system corroded

Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

MOT #18 2022-08-13 15:26

MOT test number 211207098396

Result ✓ Passed

MOT #17 2021-08-27 08:05

MOT test number 431954435022

Result ✓ Passed

Advice Car been sitting for a while

**MOT #16**

2019-07-18 15:04

MOT test number

703916408583

Result

✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Nearside Non obligatory mirror damaged**Advice** Offside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**MOT #15**

2019-07-18 15:04

MOT test number

892240099399

Result

✗ Failed

Advice Nearside Non obligatory mirror damaged**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Lower Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #14**

2018-05-10 14:24

MOT test number

892058411279

Result

✓ Passed

Advice Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #13**

2018-04-20 10:50

MOT test number

598341047515

Result

✗ Failed

Advice Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Fail** Horn not working (1.6.2a)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Offside Rear Radius arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**MOT #12**

2017-04-18 15:56

MOT test number

779118008931

Result

✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

**MOT #11** 2017-04-18 15:56**MOT test number** 104410115331**Result** ✗ Failed**Pass with rectification** Bonnet cannot be secured in the closed position (8.4.1)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Nearside Front Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #10** 2015-12-24 11:25**MOT test number** 766643926863**Result** ✓ Passed**Advice** Nearside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Rear Sub-frame rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #9** 2014-12-18 10:11**MOT test number** 217722554319**Result** ✓ Passed

**MOT #8** 2014-12-17 14:42**MOT test number** 466001554337**Result** ✗ Failed**Fail** Nearside Rear rear brake excessively fluctuating (3.7.B.3)**Fail** Nearside Front front brake excessively fluctuating (3.7.B.3)**Fail** Service brake: efficiency below requirements (3.7.B.7)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**Fail** Offside Rear rear brake excessively fluctuating (3.7.B.3)**Fail** Offside Front front brake excessively fluctuating (3.7.B.3)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #7** 2013-12-10 14:03**MOT test number** 816094143367**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Vehicle's internal headlight adjuster altered to recheck lights**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Bonnet catch and secondary catch stiff

**MOT #6** 2013-12-10 11:33**MOT test number** 267604343357**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Items removed from driver's view prior to test
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Notice** Bonnet catch and secondary catch stiff
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #5 2012-12-04 09:48**MOT test number** 479139532339**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2012-12-03 15:24**MOT test number** 555588232340**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Under-trays fitted obscuring some underside components**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2011-12-22 13:08**MOT test number** 545766051328**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-12-23 11:50**MOT test number** 612767050323**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



MOT #1	2010-01-05 15:01
MOT test number	330015000008
Result	✓ Passed
Notice	N/s/f wiper rear wiper
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
26 August 2024

Tax status		Valid until 1 October
Days left		155
MOT expiry date		26 August 2024
Full MOT history		See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EF56XXE
Plate since	2019-03-29
Current registration	EF56XXE
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2007-01-04
Last registration	2023-08-12
Complete history	See info



Registration #1	2007-01-04	12 mi
Registration #2	2010-01-05	37.446 mi
Registration #3	2010-12-23	46.388 mi
Registration #4	2011-12-22	53.422 mi
Registration #5	2012-12-03	58.668 mi
Registration #6	2012-12-04	58.669 mi
Registration #7	2013-12-10	68.415 mi
Registration #8	2013-12-10	68.415 mi
Registration #9	2014-12-17	75.056 mi
Registration #10	2014-12-18	75.056 mi
Registration #11	2015-12-24	84.031 mi
Registration #12	2016-12-29	93.007 mi
Registration #13	2017-12-29	102.007 mi
Registration #14	2018-12-29	111.007 mi
Registration #15	2019-12-29	120.007 mi
Registration #16	2020-12-29	129.007 mi
Registration #17	2021-12-29	138.007 mi
Registration #18	2022-12-29	147.007 mi
Registration #19	2023-12-29	156.007 mi
Registration #20	2024-03-29	165.007 mi
Registration #21	2024-03-29	165.007 mi
Registration #22	2024-03-29	165.007 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	1ZZU948780