



OW56LNN

report date: 2024-03-29

General information

Make	MAZDA
Model	5 D TS2 7STR
Colour	Blue
Year of manufacture	-
Top speed	111 mph
0 - 60 mph	12.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	310 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	49.6 mpg
Consumption combined	44.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-29
Pictures	6
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT #13	2020-12-21 11:02
MOT test number	245329133822
Result	✓ Passed
Next expiry date	2022-01-10

MOT #12	2020-01-11 09:16
MOT test number	331215227499
Result	✓ Passed

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2018-06-15 14:52
MOT test number	162226069169
Result	✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

MOT #10	2017-06-16 15:42
MOT test number	398502841828
Result	✓ Passed

Advice Exhaust corroded

Advice Radiator leaking

Advice Nearside rear tyre worn on inner edge

Advice Corrosion to rear sub-frame

Advice Offside tyre inner edge worn bald (strong advisory)

**MOT #9** 2017-06-09 16:00**MOT test number** 176178810647**Result** ✗ Failed**Advice** Offside tyre inner edge worn bald (strong advisory)**Fail** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)**Advice** Exhaust corroded**Advice** Offside Front Lower Suspension arm has slight play in a pin/bush (2.4.G.2)**Advice** Radiator leaking**Advice** Nearside rear tyre worn on inner edge**Fail** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)**Advice** Corrosion to rear sub-frame**MOT #8** 2016-06-07 11:00**MOT test number** 847523668454**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #7** 2015-02-05 09:19**MOT test number** 838066635090**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #6**

2014-02-13 10:29

MOT test number

527034944068

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #5**

2013-02-19 14:27

MOT test number

789440553076

Result

✓ Passed

Notice Under-trays fitted obscuring some underside components**Notice** E s c light on**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4**

2012-02-20 13:33

MOT test number

738271852050

Result

✓ Passed

Notice Knock from front suspension**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Outter end of offside wiper blade split**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Under-trays fitted obscuring some underside components

**MOT #3** 2011-02-21 11:41**MOT test number** 119442251085**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-02-05 10:13**MOT test number** 840906830031**Result** ✓ Passed**Notice** Front pads getting low**Notice** Cage in rear rear/rear seat belts not fully checked**MOT #1** 2010-02-05 10:13**MOT test number** 192256330483**Result** ✗ Failed**Notice** Front pads getting low**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** Cage in rear rear/rear seat belts not fully checked



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2007-02-23
Last registration	2020-12-21
Complete history	See info



Registration #1	2007-02-23	21 mi
Registration #2	2010-02-05	27.016 mi
Registration #3	2011-02-21	36.218 mi
Registration #4	2012-02-20	43.678 mi
Registration #5	2013-02-19	50.660 mi
Registration #6	2014-02-13	59.005 mi
Registration #7	2015-02-05	69.670 mi
Registration #8	2016-02-05	75.277 mi
Registration #9	2017-02-05	80.277 mi
Registration #10	2018-02-05	85.277 mi
Registration #11	2019-02-05	90.277 mi
Registration #12	2020-02-05	95.277 mi
Registration #13	2021-02-05	100.277 mi
Registration #14	2022-02-05	105.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Kerb weight	1645 kg
Max. allowed weight	2225 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	RF 261439