



report date: 2024-03-29

General information

Make	MINI
Model	ONE
Colour	Green
Year of manufacture	2005
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	90 BHP
Max. torque	140 Nm at 3.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.7 mpg
CO2 emission	187 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-02-02
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-03-26
MOT pass rate	68 %
MOT passed	17
Failed MOT tests	8
Total advice items	73
Total items failed	10

MOT #25	2024-03-27 14:23
MOT test number	798924280892
Result	✓ Passed
Next expiry date	2025-03-26
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))
Advice	Oil leak, but not excessive engine oil leaking (8.4.1 (a) (i))

MOT #24	2024-03-21 14:36
MOT test number	782935323051
Result	✗ Failed
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge edge worn (5.2.3 (e))
MAJOR	Engine MIL inoperative or indicates a malfunction engine light on (8.2.1.2 (h))
MAJOR	Nearside Front Lower Suspension arm pin or bush excessively worn arm rear bush ex play (5.3.4 (a) (i))
DANGEROUS	Front Bumper likely to become detached (6.1.4 (a) (ii))
MAJOR	Nearside Front Hazard warning lamps inoperative not working (4.4.1 (e))
MAJOR	Nearside Front Direction indicator not working (4.4.1 (a) (ii))
Advice	Oil leak, but not excessive engine oil leaking (8.4.1 (a) (i))

**MOT #23**

2023-03-02 18:01

MOT test number

755178498264

Result

✓ Passed

- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Rear suspension corroded
- Advice** Offside Rear Exhaust mounting defective (6.1.2 (a))
- Advice** Coolant leak water pump area
- Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a))

MOT #22

2022-03-03 17:54

MOT test number

244200984559

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a))

**MOT #21**

2022-03-02 16:49

MOT test number

138443001895

Result**✗ Failed****Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Oil leak, but not excessive engine (8.4.1 (a) (i))**MAJOR** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**Advice** Front Power steering pipe/hose has slight seepage (2.1.5 (a))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MAJOR** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #20**

2021-02-26 16:42

MOT test number

570357775066

Result**✓ Passed****MOT #19**

2021-02-26 14:18

MOT test number

773252236735

Result**✗ Failed****MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**MOT #18**

2020-07-22 07:46

MOT test number

188856432151

Result**✓ Passed**

**MOT #17** 2019-04-24 13:53**MOT test number** 931090564292**Result** ✓ Passed

- Advice** Nearside Track rod end ball joint has slight play (2.1.3 (b) (i))
- Minor** Windscreen damaged but not adversely affecting driver's view stone chip. (3.2 (a) (i))
- Advice** Coolant low & oil level low.
- Advice** Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake fluid poor condition.
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #16 2018-04-12 13:44**MOT test number** 905698788165**Result** ✓ Passed**MOT #15** 2018-04-10 15:32**MOT test number** 756711654684**Result** ✗ Failed

- Advice** Nearside Front Direction indicator slightly discoloured bulb colour is deteriorating (1.4.A.2f)
- Advice** Rear sections of the offside and nearside front to rear brake pipes are corroded
- Advice** Offside Front Tyre worn close to the legal limit 175/65x15 84 H) (non run flats fitted (4.1.E.1)
- Fail** Brake performance not tested due to a seriously damaged road wheel (3.7.A.1)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front Road wheel badly damaged SERIOUSLY DAMAGED (4.2.A.1a)

**MOT #14**

2017-04-21 11:36

MOT test number

182753777771

Result

✓ Passed

- Advice** Rear Brake pipe slightly corroded (3.6.B.2c)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice** Nearside Front tyre wearing on edges
- Advice** Body has slight corrosion (6.1.B.2)
- Advice** Offside Front tyre wearing on edges
- Advice** Front Brake pipe slightly corroded to rear (3.6.B.2c)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear (2.4.G.2)
- Advice** Offside Front tyre wearing on edges

MOT #13

2016-04-22 08:17

MOT test number

251678241109

Result

✓ Passed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

MOT #12

2016-04-18 15:25

MOT test number

124730287509

Result

✗ Failed

- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail** Parking brake lever has no reserve travel (3.1.6b)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)

MOT #11

2014-11-10 10:06

MOT test number

458134314452

Result

✓ Passed

**MOT #10** 2014-11-10 10:06**MOT test number** 135424814387**Result** ✗ Failed**Pass with rectification** Nearside Parking brake lever has no reserve travel (3.1.6b)**Pass with rectification** Exhaust has a major leak of exhaust gases (7.1.2)**Pass with rectification** Nearside rear brake binding (3.7.B.1)**MOT #9** 2013-10-07 11:44**MOT test number** 348180983413**Result** ✓ Passed**MOT #8** 2012-10-05 10:04**MOT test number** 205119172228**Result** ✓ Passed**Notice** Offside rear tyre close to legal limit**MOT #7** 2011-10-18 16:12**MOT test number** 346601891446**Result** ✓ Passed**Notice** Rear wiper blade split**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Engine oil low



MOT #6 2011-10-17 11:34

MOT test number 198510491297

Result ✗ Failed

Notice Coolant low

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Coolant leak

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Notice Rear wiper blade split

Notice Engine oil low

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #5 2011-10-07 10:20

MOT test number 879180381252

Result ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Exhaust has part of the system slightly deteriorated (7.1.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2011-10-06 11:51**MOT test number** 708299771273**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Exhaust system not adequately supported (7.1.1)**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-10-12 11:33**MOT test number** 664755980233**Result** ✓ Passed**MOT #2** 2009-09-25 10:43**MOT test number** 322498769273**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear brake disc slightly pitted (3.5.1h)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #1	2008-10-08 10:51
MOT test number	992872988255
Result	✓ Passed
Notice	Front wipers split but still clear screen
Notice	Power steering pipes damp



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 March 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	26 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YR55ONP
Plate since	2019-09-29
Current registration	YR55ONP
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2005-10-11
Last registration	2024-03-27
Complete history	See info



Registration #1	2005-10-11	24 mi
Registration #2	2008-10-08	28.299 mi
Registration #3	2009-09-25	33.187 mi
Registration #4	2010-10-12	36.589 mi
Registration #5	2011-10-06	38.626 mi
Registration #6	2011-10-07	38.628 mi
Registration #7	2011-10-17	38.664 mi
Registration #8	2011-10-18	38.665 mi
Registration #9	2012-10-05	47.940 mi
Registration #10	2013-10-07	56.011 mi
Registration #11	2014-11-10	63.179 mi
Registration #12	2016-04-18	75.882 mi
Registration #13	2016-04-22	75.882 mi
Registration #14	2016-05-20	75.882 mi
Registration #15	2016-06-20	75.882 mi
Registration #16	2016-07-20	75.882 mi
Registration #17	2016-08-20	75.882 mi
Registration #18	2016-09-20	75.882 mi
Registration #19	2016-10-20	75.882 mi
Registration #20	2016-11-20	75.882 mi
Registration #21	2016-12-20	75.882 mi
Registration #22	2017-01-20	75.882 mi
Registration #23	2017-02-20	75.882 mi
Registration #24	2017-03-20	75.882 mi
Registration #25	2017-04-20	75.882 mi
Registration #26	2017-05-20	75.882 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1925 mm
Height	1416 mm
Length	3635 mm
Wheel base	2467 mm
Kerb weight	1155 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Engine number	D3750613
---------------	----------