



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	C-HR DESIGN
Colour	White
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	11.0 seconds
Gearbox	1 speed CVT

Engine & fuel consumption

Power	97 BHP
Max. torque	142 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	83.1 mpg
Consumption extra urban	70.6 mpg
Consumption combined	74.3 mpg
CO2 emission	86 g/km
CO2 label	A





## Internet history

### Entry 2


Date	2021-10-26
Pictures	34
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)

### Entry 1

Date	2021-09-04
Pictures	5
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2025-04-07
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	8
Total items failed	6

MOT #7	2024-04-08 14:57
MOT test number	608879335429
Result	✓ Passed
Next expiry date	2025-04-07
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #6** 2024-04-04 14:44**MOT test number** 435727566515**Result** ✗ Failed**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Headlamps matched pair are not the same colour (4.1.4 (d))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #5** 2023-03-16 16:14**MOT test number** 764167283736**Result** ✓ Passed**Advice** Both front tyres 3mm and wearing on edges 225/50/18v**MOT #4** 2022-04-02 10:14**MOT test number** 276501845897**Result** ✓ Passed**MOT #3** 2021-09-14 14:28**MOT test number** 821982029412**Result** ✓ Passed



MOT #2	2021-06-15 13:18
MOT test number	653251157113
Result	✓ Passed

MOT #1	2021-06-15 13:18
MOT test number	337919130769
Result	✗ Failed

Pass with rectification

 Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
7 April 2025

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	7 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	59
<b>Band</b>	D
<b>First licence fee (12 months)</b>	£ 120,00,-
<b>Standard rate (12 months)</b>	£ 170,00,-
<b>Standard rate (6 months)</b>	£ 93,50,-
<b>Premium rate (12 months)</b>	£ 560,00,-
<b>Premium rate (6 months)</b>	£ 308,00,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	<b>EG18XEB</b>
Plate since	2019-09-29
Current registration	<b>EG18XEB</b>
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2018-08-24
Last registration	2024-04-08
Complete history	<a href="#">See info</a>



Registration #1	2018-08-24	22 mi
Registration #2	2021-06-15	23.143 mi
Registration #3	2021-06-15	23.143 mi
Registration #4	2021-06-15	23.143 mi
Registration #5	2021-09-14	27.040 mi
Registration #6	2021-09-14	27.040 mi
Registration #7	2021-09-14	27.040 mi
Registration #8	2021-09-14	27.040 mi
Registration #9	2021-09-14	27.040 mi
Registration #10	2021-09-14	27.040 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	77%
Pedestrian	76%
Safety systems	78%
Overall rating	84%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1795 mm
Height	1565 mm
Length	4360 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	43 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Engine number**

2ZR2B41172