



RENAULT



report date: 2024-03-29

General information

Make	RENAULT
Model	CLIO DYNAMIQUE 16V
Colour	Blue
Year of manufacture	-
Top speed	114 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 BHP
Max. torque	127 Nm at 4.250 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	52.3 mpg
Consumption combined	42.8 mpg



LABEL UNKNOWN



MOT history

MOT #18 2021-11-05 17:28**MOT test number** 447875250659**Result** ✓ Passed**Next expiry date** 2022-11-04

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #17 2021-11-02 09:15**MOT test number** 971365093362**Result** ✗ Failed

Fail Offside Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16 2020-06-23 10:51**MOT test number** 829425363323**Result** ✗ Failed

Fail Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #15 2020-06-23 10:47**MOT test number** 783755503324**Result** ✓ Passed**MOT #14** 2019-07-16 09:44**MOT test number** 386328009449**Result** ✓ Passed

**MOT #13** 2018-07-10 08:25**MOT test number** 991762340955**Result** ✓ Passed**MOT #12** 2017-07-05 14:37**MOT test number** 851066652290**Result** ✓ Passed**MOT #11** 2017-07-05 10:12**MOT test number** 210493899988**Result** ✗ Failed**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #10** 2016-07-19 12:04**MOT test number** 928985155327**Result** ✓ Passed**MOT #9** 2016-07-12 08:38**MOT test number** 747213129075**Result** ✗ Failed**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #8** 2015-07-06 11:26**MOT test number** 215657385404**Result** ✓ Passed

**MOT #7** 2014-07-18 10:30**MOT test number** 559079294143**Result** ✓ Passed**MOT #6** 2013-07-08 15:16**MOT test number** 397069583169**Result** ✓ Passed**MOT #5** 2012-07-18 10:57**MOT test number** 367090102222**Result** ✓ Passed**MOT #4** 2011-07-15 12:01**MOT test number** 877736691176**Result** ✓ Passed**MOT #3** 2010-07-02 12:44**MOT test number** 143933780123**Result** ✓ Passed**Advice** Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2010-06-11 09:29**MOT test number** 242082260417**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1	2010-06-03 14:53
MOT test number	281944850481
Result	✗ Failed
Fail	Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)
Fail	Centre Rear Seat belt locking mechanism does not secure or release (5.2.5a)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	KB07XUA
Plate since	2024-03-29
Current registration	KB07XUA
Plate since	2024-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-06-14
Last registration	2021-11-05
Complete history	See info



Registration #1	2007-06-14	24 mi
Registration #2	2010-06-03	15.419 mi
Registration #3	2010-06-11	15.609 mi
Registration #4	2010-07-02	15.868 mi
Registration #5	2011-07-15	24.261 mi
Registration #6	2012-07-18	34.665 mi
Registration #7	2013-07-08	44.787 mi
Registration #8	2014-07-18	54.804 mi
Registration #9	2015-07-06	63.330 mi
Registration #10	2016-07-12	71.155 mi
Registration #11	2016-07-12	71.155 mi
Registration #12	2016-07-12	71.155 mi
Registration #13	2016-07-12	71.155 mi
Registration #14	2016-07-12	71.155 mi
Registration #15	2016-07-12	71.155 mi
Registration #16	2016-07-12	71.155 mi
Registration #17	2016-07-12	71.155 mi
Registration #18	2016-07-12	71.155 mi
Registration #19	2016-07-12	71.155 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1940 mm
Height	1496 mm
Length	3986 mm
Wheel base	2575 mm
Kerb weight	1135 kg
Max. allowed weight	1625 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D078306
---------------	---------